

ASFYJQ

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------|------------------------|--------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: DIRTY [x] |
| Owner : | | Mileage : | 66620 KM |
| File nr. : | 1387030 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1EWM283 / WAUZZZ8K0DA227256 / | | yr of constructionr : | 2013 / 00 |
| E-File nr. : | | First registration : | 08/04/2013 |
| VFS-nr. : | | Color : | GREY |
| Make + Model : | AUDI / A4 | Fuel type : | DIESEL |
| Object nr. : | 55966 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | CARDIO3 BIOSCIENCES SA | Co2: | 112g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | | Seats (minivan) : | 0 |
| Vehicle type : | A4 BER TDie 136PK | Country registration : | BELGIUM |

| | | | |
|------------------------------|---------|---------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | BERLINE | Engine size: | 1968 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 4 |
| HP: | 136 | kW: | 100 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | | Smoked in vehicle: | |
| Due date vehicle inspection: | | Extra set of tires: | |
| | | Use: | Unknown |

| | |
|--------------------|--|
| General condition: | |
|--------------------|--|

| | |
|-------------------------------------|---------------------------|
| Original registr. number : OK | Service manual : OK [x] |
| Cert. of reg. / Part 1: | Cert. of conformity : OK |
| Cert. of reg. copy / Part 2: OK [x] | Insurance certificate : |
| Warning vest : | Transport licence : |
| Tax certificate : | Navigation CD/SD/DVD |
| Fuel card : | Car radio : OK [x] |
| Mobile phone kit : | Extinguisher : OK [x] |
| | Warning triangle : OK [x] |
| First aid kit : OK [x] | Oil level : OK [x] |
| Jack, wheelspanner : | Filled up : 0 |

Wheels and tyres: Winter tires

| | | | | | | | | | |
|------------|-----|----------|--------|-----|-----|-------|-------|--------------------------------|----------------|
| Wheel FL: | [x] | MICHELIN | Tyre : | OK | [x] | 4-6 / | Rim : | / | Hubcap : |
| Wheel RL : | [x] | MICHELIN | Tyre : | OK | [x] | >6 / | Rim : | / | Hubcap : |
| Wheel FR : | [x] | MICHELIN | Tyre : | [x] | OK | [x] | 4-6 / | Rim : | [x] / Hubcap : |
| Wheel RR : | [x] | MICHELIN | Tyre : | OK | [x] | >6 / | Rim : | [x] WHEEL SCRATCHED / Hubcap : | |
| Wheel RES: | [x] | | Tyre : | OK | | / | Rim : | / Hubcap : | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205 | 60 | R | 16 | M+S |
| Rear tyre | 205 | 60 | R | 16 | M+S |

Remark :

Wheels and tyres:

| | | | | | | | |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | | |
|-----|-------------------------|--------------------------------|---------------|
| [x] | REAR DOOR/RIGHT/FRONT | DENT | |
| [x] | FRONT DOOR/RIGHT/CENTER | DENT | MET LAKSCHADE |
| [x] | BONNET/CENTER/LEFT | SCRATCH (WITHOUT PAINT DAMAGE) | |
| [x] | LIGHTS/LEFT/FRONT | SCRATCH WITH PAINT DAMAGE | |

Accessories and others

| | | |
|-----|-------------------------------|---------------------------|
| [x] | OUTSIDE MIRROR RIGHTHAND SIDE | SCRATCH WITH PAINT DAMAGE |
|-----|-------------------------------|---------------------------|

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | | |
|-----|---------------------------|---------------------------|---------------|-------|------------|
| [x] | FRONT MUDGUARD/LEFT/FRONT | SCRATCH WITH PAINT DAMAGE | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 1 | 0 LU =0.00 EUR | 220.18 EUR | | 50 % | 220.18 EUR |
| [x] | FRONT BUMPER/LEFT/SIDE | SCRATCH WITH PAINT DAMAGE | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 1 | 0 LU =0.00 EUR | 211.80 EUR | | 50 % | 211.80 EUR |

Others

RIM REAR RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|----------------------|--------------------|------------|-------|-----------|
| 2 | 11 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|-------|---|---|---|---|---|---|---|----|
| 431.98 | 95.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 215.99 | 95.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|-------------------|
| 95.00 | 431.98 | 0 | 526.98 |
| HOG: 0 | BG: 0 | | NA Deprec. 310.99 |
| | | | 0.00% |
| | | | TOTAL 310.99 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|-------------------------------|----------------------------------|---------------------------------|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|--|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 11/04/2017 Hour : 13:36 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |