

AU4QMT

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	193920 KM
File nr. :	1388306	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EUF362 / WAUZZZ8K3DA218373 /		yr of constructionr :	2013 / 00
E-File nr. :		First registration :	21/03/2013
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / A4 AVANT	Fuel type :	DIESEL
Object nr. :	62411	Fuel :	
Classification :	F	Environment Class:	EURO 5
Customer company :	Limagrain Belgium NV	Co2:	116g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	3 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	A4 AVANT TDie 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK
Jack, wheelspanner :	OK	[x]	Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	FULDA	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RL :	[x]	KLÉBER	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel FR :	[x]	FULDA	Tyre :	[x]	OK	[x]	4-6 /	Rim :	/
Wheel RR :	[x]	KLÉBER	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	M+S
Rear tyre	205	60	R	16	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/RIGHT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	FRONT THRESHOLD/LEFT/REAR	DENT	BINNENKANT
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/LEFT/CENTER	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
1	15 LU =72.00 EUR	318.35 EUR		50 %	390.35 EUR
[x]	WINDSCREEN/CENTER/RIGHT	WINDOW DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
4	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR
[x]	FRONT MUDGUARD/RIGHT/CENTER	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
3	20 LU =96.00 EUR	220.18 EUR		50 %	316.18 EUR

Interior

[x]	FLOOR BOOT			HOLE		
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-inttap-01	CARPET REPAIR (MAX 3CM LENGTH OR DIAMETER)	43.92 EUR		43.92 EUR

Pieces

	Number	Code	Description	Unit price	Depr.	Total
4	1	WIND SCREEN		367.20 EUR	50 %	367.20 EUR

1	2	3	4	5	6	7	8	9	10
390.35	43.92	316.18	487.20	0	0	0	0	0	0
195.18	43.92	158.09	243.60	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
43.92	1193.73	0	1237.65
HOG: 0	BG: 0		NA Deprec. 640.78
			0.00%
			TOTAL 640.78

APPRAISAL

www.vabfleetservices.be

Date : 12/04/2017

5/5

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min 	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 12/04/2017 Hour : 15:39	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	