

ARO4U6

☒ EFFECTIVE ☐ NOT EXECUTED ☐ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	80949 KM
File nr. :	1386470	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
CA1998 / WAUZZZ4G6EN133216 /		yr of constructionr :	/
E-File nr. :		First registration :	31/03/2014
VFS-nr. :		Color :	SILVER
Make + Model :	AUDI / A6 AVANT	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	Parthena Reys Property Holdings Sàrl	Co2:	g/km
Driver :		Remote controls:	1
Covering :	TISSUE-LEATHER	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	LUXEMBOURG

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1968
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :		Service manual :	OK
Cert. of reg. / Part 1:	[x]	Cert. of conformity :	
Cert. of reg. copy / Part 2:		Insurance certificate :	[x]
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	[x]
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
		Warning triangle :	OK
First aid kit :	OK	Oil level :	OK
Jack, wheelspanner :	OK	Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	4-6 /	Rim :	WHEEL SCRATCHED	/	Hubcap :	[x]	MISSING/INCOMPLETE
Wheel RL :	[x]	MICHELIN	Tyre :	OK	4-6 /	Rim :	WHEEL SCRATCHED	/	Hubcap :	[x]	MISSING/INCOMPLETE
Wheel FR :	[x]	MICHELIN	Tyre :	OK	4-6 /	Rim :	WHEEL SCRATCHED	/	Hubcap :	[x]	MISSING/INCOMPLETE
Wheel RR :	[x]	MICHELIN	Tyre :	OK	4-6 /	Rim :	WHEEL SCRATCHED	/	Hubcap :	[x]	MISSING/INCOMPLETE
Wheel RES:	[x]	ANDERE	Tyre :	OK	/	Rim :		/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	245	45	R	18	WINTER V
Rear tyre	245	45	R	18	WINTER V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	DENT
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE
	WINDSCREEN/CENTER/RIGHT	WINDOW DAMAGE

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	------------------------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR
[x]	FRONT MUDGUARD/LEFT/FRONT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
3	10 LU =48.00 EUR	264.21 EUR		50 %	312.21 EUR
[x]	BONNET/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	348.09 EUR		50 %	348.09 EUR
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE			SCRATCH WITH PAINT DAMAGE		
	Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

Others

RIM FRONT LEFT

	Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

HUB CAP FL

	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR			50 %	

HUB CAP REAR L

	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR			50 %	

HUB CAP REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
6	1	WHEEL CAP	36.00 EUR	50 %	36.00 EUR

Number	Code	Description	Unit price	Depr.	Total
6	1	WHEEL CAP	36.00 EUR	50 %	36.00 EUR

Number	Code	Description	Unit price	Depr.	Total
6	1	WHEEL CAP	36.00 EUR	50 %	36.00 EUR

Number	Code	Description	Unit price	Depr.	Total
6	1	WHEEL CAP	36.00 EUR	50 %	36.00 EUR

1	2	3	4	5	6	7	8	9	10
254.16	348.09	312.21	254.16	115.56	524.00	0	0	0	0
127.08	174.04	156.10	127.08	115.56	452.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
495.56	1312.62	0	1808.18
HOG: 0	BG: 2		NA Deprec. 1151.87
			0.00%
			TOTAL 1151.87

APPRAISAL

www.vabfleetservices.be

Date : 07/04/2017

6/6

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time :	0 min	Waiting time :	0 min	Towing time :	0 min
		Reason :			
NOT EXECUTED : No					
Reason :					
Remark : DOCUMENTEN WORDEN NA GESTUURD [x]					

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 07/04/2017 Hour : 10:28	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	