

ATV6WF

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	106174 KM
File nr. :	1388101	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FOT211 / WAUZZZ8X7EB021522 /		yr of constructionr :	/
E-File nr. :		First registration :	10/09/2013
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / A1 SPORTBACK	Fuel type :	DIESEL
Object nr. :	32539	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ERNST & YOUNG BEDRIJFSREVISOREN CVBA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	A1 SB Attraction 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	4
Number of gears:	5	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Winter tires

Wheel FL :	[x]	SEMPERIT	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :		
Wheel RL :	[x]	SEMPERIT	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :		
Wheel FR :	[x]	SEMPERIT	Tyre :	[x]	OK	[x]	4-6 /	Rim :		/	Hubcap :	
Wheel RR :	[x]	SEMPERIT	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

	[x]	Width	Height	Type	Rim	Index
Front tyre		205	55	R	15	WINTER H
Rear tyre		205	55	R	15	WINTER H

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] BONNET/CENTER/RIGHT/FRONT CHIPS

[x] FRONT BUMPER/RIGHT CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] WIND SCREEN/BELOW/RIGHT WINDOW DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

Others

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WIND SCREEN	293.76 EUR	50 %	293.76 EUR

1	2	3	4	5	6	7	8	9	10
413.76	95.00	0	0	0	0	0	0	0	0
206.88	95.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	413.76	0	508.76
HOG: 0	BG: 1		NA Deprec. 301.88
			0.00%
			TOTAL 301.88

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 11/04/2017 Hour : 16:47 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	