

ANG1CU

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	74123 KM
File nr. :	1383086	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ERJ525 / WBA3D11000J621901 /		yr of constructionr :	2013 / 00
E-File nr. :		First registration :	01/03/2013
VFS-nr. :		Color :	GREY
Make + Model :	BMW / 3	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	DELAWARE CONSULTING BVBA	Co2:	116g/km
Driver :		Remote controls:	2
Covering :	IMITATION LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	3 BER 318d 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK	Insurance certificate :	OK
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	[x]
		Warning triangle :	OK
First aid kit :	[x]	Oil level :	OK
Jack, wheelspanner :	OK	Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	CONTINENTAL	Tyre :	OK	4-6 /	Rim :		/	Hubcap :	
Wheel RL :	CONTINENTAL	Tyre :	OK	4-6 /	Rim :		/	Hubcap :	
Wheel FR :	CONTINENTAL	Tyre :	OK	4-6 /	Rim :	WHEEL SCRATCHED	/	Hubcap :	
Wheel RR :	CONTINENTAL	Tyre :	OK	4-6 /	Rim :	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	WINTER H
Rear tyre	205	60	R	16	WINTER H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)	MEERDERE
[x]	REAR DOOR/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR MUDGUARD/LEFT/FRONT	DENT	
[x]	REAR DOOR/LEFT/CENTER	DENT	
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS	

Accessories and others

OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-------------------------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE			
Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR
[x]	FRONT DOOR/RIGHT/CENTER	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
2	10 LU =48.00 EUR	318.35 EUR		50 %	366.35 EUR
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE		MEERDERE	
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	366.35	115.56	0	0	0	0	0	0	0
105.90	183.18	115.56	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
115.56	578.15	0	693.71
HOG: 0	BG: 0		NA Deprec. 404.64
			0.00%
			TOTAL 404.64

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : ELEKTRONISCHE ONDERHOUDSBOEKJE/NAVI OK		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 03/04/2017 Hour : 16:49 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	