

ARU3KS

☒ EFFECTIVE ☐ NOT EXECUTED ☐ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	204188 KM
File nr. :	1386603	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
CU4827 / WAUZZZ8U9ER025150 /		yr of constructionr :	/
E-File nr. :		First registration :	30/09/2013
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / Q3	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	EUROSOFT CONSULTING SA	Co2:	g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	Q3 140PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	SUV	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	140	kW:	103
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	Service manual :	NOK	☐
Cert. of reg. / Part 1:	Cert. of conformity :		
Cert. of reg. copy / Part 2:	Insurance certificate :		
Warning vest :	Transport licence :		
Tax certificate :	Navigation CD/SD/DVD		
Fuel card :	Car radio :	OK	☐
Mobile phone kit :	Extinguisher :	OK	☐
	Warning triangle :	OK	☐
First aid kit :	Oil level :	OK	☐
Jack, wheelspanner :	Filled up :	0	

Wheels and tyres: Winter tires

Wheel FL:	☐	UNIROYAL	Tyre :	OK	☐	2-4 /	Rim :		/	Hubcap :	
Wheel RL :	☐	UNIROYAL	Tyre :	OK	☐	2-4 /	Rim :		/	Hubcap :	
Wheel FR :	☐	UNIROYAL	Tyre :	☐	OK	☐	2-4 /	Rim :		/	Hubcap :
Wheel RR :	☐	UNIROYAL	Tyre :	OK	☐	2-4 /	Rim :		/	Hubcap :	
Wheel RES:	☐		Tyre :	OK		/	Rim :		/	Hubcap :	

☐	Width	Height	Type	Rim	Index
Front tyre	235	55	R	17	M+S
Rear tyre	235	55	R	17	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

☐	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	WINDSCREEN/CENTER/RIGHT	WINDOW DAMAGE	HERSTELD
[x]	FRONT MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	

Interior

[x]	FLOOR BOOT	OTHER DAMAGES
-----	------------	---------------

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 0		NA Deprec. 0
			0.00%
			TOTAL 0

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : DOCUMENTEN WORDEN NAGESTUURD [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 05/04/2017 Hour : 11:56 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	