

AQ4CWH

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------|---------------------------------|--------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 90443 KM |
| File nr. : | 1385226 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1GHS487 / WDD2040021A941139 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 11/02/2014 |
| VFS-nr. : | | Color : | GREY |
| Make + Model : | MERCEDES / C | Fuel type : | DIESEL |
| Object nr. : | | Fuel : | |
| Classification : | K | Environment Class: | EURO 5 |
| Customer company : | BEAULIEU INTERNATIONAL GROUP NV | Co2: | 109g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | PARTIAL LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | | Seats (minivan) : | 0 |
| Vehicle type : | | Country registration : | BELGIUM |

| | | | |
|------------------------------|---------|---------------------|---------|
| VAT over the margin - car: | | Metallic paint: | Yes |
| Variant car: | BERLINE | Engine size: | 2143 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 4 |
| HP: | 163 | kW: | 120 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |
| General condition: | | | |

| | | | | |
|------------------------------|----|-------------------------|-----------------------|-----|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | OK | [x] | Cert. of conformity : | OK |
| Cert. of reg. copy / Part 2: | | Insurance certificate : | | |
| Warning vest : | | Transport licence : | | |
| Tax certificate : | | Navigation CD/SD/DVD | | |
| Fuel card : | | Car radio : | OK | [x] |
| Mobile phone kit : | | Extinguisher : | | |
| First aid kit : | | Warning triangle : | OK | [x] |
| Jack, wheelspanner : | OK | [x] | Oil level : | OK |
| | | | Filled up : | 0 |

Wheels and tyres: Winter tires

| | | | | | | | | | | | | |
|------------|-----|-------------|--------|-----|-----|-------|-------|-------|-----------------|-----------------|----------|----------|
| Wheel FL: | [x] | CONTINENTAL | Tyre : | OK | [x] | 4-6 / | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : | |
| Wheel RL : | [x] | CONTINENTAL | Tyre : | OK | [x] | 4-6 / | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : | |
| Wheel FR : | [x] | CONTINENTAL | Tyre : | [x] | OK | [x] | 4-6 / | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : |
| Wheel RR : | [x] | CONTINENTAL | Tyre : | OK | [x] | 4-6 / | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : | |
| Wheel RES: | [x] | CONTINENTAL | Tyre : | OK | [x] | >6 / | Rim : | | | / | Hubcap : | |

| | | | | | |
|------------|-------|--------|------|-----|-------|
| [x] | Width | Height | Type | Rim | Index |
| Front tyre | 205 | 55 | R | 16 | M+S |
| Rear tyre | 205 | 55 | R | 16 | M+S |

Remark :

Wheels and tyres:

| | | | | | | | | |
|------------|--|--------|----|---|-------|--|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | | / | Hubcap : |

| | | | | | |
|------------|-------|--------|------|-----|-------|
| [x] | Width | Height | Type | Rim | Index |
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

Conclusion

Bodywork \& windows

[x] BONNET/CENTER/LEFT/FRONT CHIPS

[x] BONNET/CENTER/RIGHT/FRONT CHIPS

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR BUMPER/CENTER/RIGHT SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR DOOR/RIGHT/REAR SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

| | Number | Code | Description | Unit price | Depr. | Total |
|---|--------|-------------|-------------|------------|-------|------------|
| 1 | I 1 | i-vab-sp-01 | SPOTREPAIR | 115.56 EUR | | 115.56 EUR |

Others

RIM REAR RIGHT

| | Number | Code | Description | Unit price | Depr. | Total |
|---|--------|-------------------|--------------------|------------|-------|-----------|
| 2 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR |

RIM FRONT RIGHT

| | Number | Code | Description | Unit price | Depr. | Total |
|---|--------|-------------------|--------------------|------------|-------|-----------|
| 2 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|--------|---|---|---|---|---|---|---|----|
| 115.56 | 190.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 115.56 | 190.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|-------------------|
| 305.56 | 0 | 0 | 305.56 |
| HOG: 0 | BG: 0 | | NA Deprec. 305.56 |
| | | | 0.00% |
| | | | TOTAL 305.56 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|-------------------------------|----------------------------------|---------------------------------|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|--|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 07/04/2017 Hour : 11:37 Company : KATHLEEN DHAENE Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |