

ARD9DR

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	214791 KM
File nr. :	1386250	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1AAK649 / WVWZZZ1KZBW097024 /		yr of constructionr :	/
E-File nr. :		First registration :	17/11/2010
VFS-nr. :		Color :	
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :	33609	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	MEURA SA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	GOLF BER BlueMotion DPF 105PK	Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	5-speed manual gearbox	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK			Service manual :	OK	[x]
Cert. of reg. / Part 1:				Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]		Insurance certificate :		
Warning vest :	OK	[x]		Transport licence :		
Tax certificate :				Navigation CD/SD/DVD		
Fuel card :				Car radio :	OK	[x]
Mobile phone kit :				Extinguisher :	OK	[x]
				Warning triangle :	OK	[x]
First aid kit :	OK	[x]		Oil level :	OK	[x]
Jack, wheelspanner :				Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :		
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :		
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4 /	Rim :		/	Hubcap :	
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :	[x]	SCRATCHED
Wheel RES:	[x]	ANDERE	Tyre :	OK		/	Rim :		/	Hubcap :		

	[x]	Width	Height	Type	Rim	Index
Front tyre		195	65	R	15	H
Rear tyre		195	65	R	15	H

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork l& windows

[x]	REAR DOOR/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/LEFT/FRONT	DENT
[x]	REAR WINDOW STYLE/LEFT/FRONT	DENT
[x]	ROOF/REAR/LEFT	DENT
[x]	FRONT DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	ROOF STYLE/FRONT/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/LEFT	CHIPS

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	SCRATCH WITH PAINT DAMAGE
[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork l& windows

[x]	REAR BUMPER/CENTER/LEFT			SCRATCH WITH PAINT DAMAGE		
			Repair paint - LI	New paint - E	Depr.	Total
4	10 LU =48.00 EUR		0 EUR		50 %	48.00 EUR
			Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR		211.80 EUR		50 %	211.80 EUR
[x]	REAR THRESHOLD/RIGHT/REAR			DENT		
			Repair paint - LI	New paint - E	Depr.	Total
5	20 LU =96.00 EUR		310.50 EUR		50 %	406.50 EUR
[x]	WINDSCREEN/CENTER/RIGHT			WINDOW DAMAGE		
	Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-herstr-01	WINDOW REPAIR	58.80 EUR	50 %	58.80 EUR
[x]	FRONT MUDGUARD/LEFT/REAR			SCRATCH WITH PAINT DAMAGE		
			Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR		220.18 EUR		50 %	220.18 EUR

[x] FRONT BUMPER/RIGHT

SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Interior

[x] FLOOR FL

HOLE

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-inttap-01	CARPET REPAIR (MAX 3CM LENGTH OR DIAMETER)	43.92 EUR	43.92 EUR

[x] SEAT FL

CUT / TORN

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-intvtr-01	VELOURS REPAIR (MAX 3CM LENGTH OR DIAMETER)	64.32 EUR	64.32 EUR

Others

CLEANLINESS INTERIOR

	Repair paint - LI	New paint - E	Depr.	Total
1 5 LU =24.00 EUR			50 %	24.00 EUR

HUB CAP REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
6	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
132.24	211.80	220.18	259.80	406.50	88.80	0	0	0	0
120.24	105.90	110.09	129.90	203.25	44.40	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
167.04	1152.28	0	1319.32
HOG: 0	BG: 0		NA Deprec. 713.78
			0.00%
			TOTAL 713.78

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/04/2017 Hour : 13:23 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	