

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	97413 KM
File nr. :	1387238	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EAB059 / WVWZZZ1KZDW085732 /		yr of constructionr :	/
E-File nr. :		First registration :	01/10/2012
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :	4067	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ERNST YOUNG ACCOUNTANCY AND TAX SERVICES	Co2:	99g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	GOLF BER BlueMotion DPF 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	NOK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	[x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	DUNLOP	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RL :	[x]	DUNLOP	Tyre :	OK	[x]	4-6 /	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :
Wheel FR :	[x]	DUNLOP	Tyre :	[x]	OK	[x]	4-6 /	Rim :	[x] WHEEL SCRATCHED / Hubcap :
Wheel RR :	[x]	DUNLOP	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	H
Rear tyre	195	65	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/LEFT/FRONT DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	MEERDERE	
		Repair paint - LI	New paint - E	Depr.
				Total
8	0 LU =0.00 EUR	211.80 EUR	50 %	211.80 EUR
[x]	REAR WINDOW/LEFT	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.
				Total
10	0 LU =0.00 EUR	0 EUR	50 %	
		Repair paint - LI	New paint - E	Depr.
				Total
10	25 LU =120.00 EUR	0 EUR	50 %	120.00 EUR
[x]	REAR MUDGUARD/RIGHT/CENTER	OTHER DAMAGES	CEMENT	
		Repair paint - LI	New paint - E	Depr.
				Total
7	0 LU =0.00 EUR	308.20 EUR	50 %	308.20 EUR
[x]	ROOF/CENTER/RIGHT	OTHER DAMAGES	CEMENT	
		Repair paint - LI	New paint - E	Depr.
				Total
3	0 LU =0.00 EUR	481.50 EUR	50 %	481.50 EUR
[x]	REAR DOOR/RIGHT/CENTER	OTHER DAMAGES	CEMENT	
		Repair paint - LI	New paint - E	Depr.
				Total
6	0 LU =0.00 EUR	318.35 EUR	50 %	318.35 EUR
[x]	WINDOW FRONT DOOR/RIGHT	OTHER DAMAGES	CEMENT	
		Repair paint - LI	New paint - E	Depr.
				Total
5	0 LU =0.00 EUR	0 EUR	50 %	
		Repair paint - LI	New paint - E	Depr.
				Total
5	10 LU =48.00 EUR	0 EUR	50 %	48.00 EUR
[x]	FRONT MUDGUARD/LEFT/FRONT	DENT		
		Repair paint - LI	New paint - E	Depr.
				Total
9	0 LU =0.00 EUR	220.18 EUR	50 %	220.18 EUR

[x]	BONNET/CENTER/LEFT	OTHER DAMAGES	CHEM. INWERKING + CEMENT	
		Repair paint - LI	New paint - E	Depr. Total
2	0 LU =0.00 EUR	290.08 EUR		50 % 290.08 EUR
[x]	FRONT MUDGUARD/RIGHT/REAR	OTHER DAMAGES	CEMENT	
		Repair paint - LI	New paint - E	Depr. Total
4	0 LU =0.00 EUR	220.18 EUR		50 % 220.18 EUR
[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr. Total
9	0 LU =0.00 EUR	211.80 EUR		50 % 211.80 EUR
[x]	FRONT BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr. Total
0	0			

Others

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
5	1	ZIJRUIT	150.00 EUR	50 %	150.00 EUR
Number	Code	Description	Unit price	Depr.	Total
10	1	BACK WINDOW	250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
190.00	290.08	481.50	220.18	198.00	318.35	308.20	211.80	431.98	370.00
190.00	145.04	240.75	110.09	99.00	159.18	154.10	105.90	215.99	185.00

INNOVATIVE	TRADITIONAL	GENERAL	
190.00	2830.09	0	3020.09
HOG: 0	BG: 0		NA Deprec. 1605.04
			0.00%
			TOTAL 1605.04

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/04/2017 Hour : 09:01 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	