

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	119397 KM
File nr. :	1387149	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EPG418 / 2C4RLAC50CR273011 /		yr of constructionr :	2013 / 00
E-File nr. :		First registration :	13/02/2013
VFS-nr. :		Color :	BLACK
Make + Model :	LANCIA / ONBEKEND	Fuel type :	DIESEL
Object nr. :	52290	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	LIMBURGSE RECONVERSIE MAATSCHAPPIJ NV	Co2:	207g/km
Driver :		Remote controls:	2
Covering :	ALCANTARA	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	7 [x]
Vehicle type :	VOYAGER Platinum Line 163PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	2776
Gear box :	Automaat algemeen	Number of places:	7
Number of gears:		Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK
				[x]
Jack, wheelspanner :		Filled up :	0	

Wheels and tyres: Winter tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	>6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	>6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	65	R	17	M+S
Rear tyre	225	65	R	17	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork l& windows

[x] FRONT DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

Interior

[x] SEAT REAR L SCRATCHED

STATUS: NOT ACCEPTABLE

Bodywork l& windows

[x] REAR BUMPER /LEFT/CORNER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x] REAR DOOR/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR	301.68 EUR		50 %	301.68 EUR

[x] REAR MUDGUARD/LEFT/FRONT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR

[x] REAR WINDOW STYLE/CENTER/LEFT/UP SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
7 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR

[x] REAR MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
8 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR

[x] REAR DOOR/LEFT/FRONT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] REAR DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
8 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] FRONT DOOR/LEFT/CENTER

SCRATCH WITH PAINT DAMAGE

		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] WINDSCREEN/CENTER/LEFT

WINDOW DAMAGE

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR
Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-herstr-02	SUPPL WINDOW REPAIR	29.40 EUR		29.40 EUR

[x] FRONT MUDGUARD/LEFT/REAR

SCRATCH WITH PAINT DAMAGE

		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

[x] FRONT MUDGUARD/RIGHT/CENTER

SCRATCH WITH PAINT DAMAGE

		Repair paint - LI	New paint - E	Depr.	Total
9	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

[x] BONNET/CENTER/LEFT/FRONT

DENT

+ KRASSEN NIET DOOR LAK

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x] FRONT BUMPER/RIGHT/SIDE

SCRATCH WITH PAINT DAMAGE

		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	63.00	88.20	1165.08	211.80	301.68	308.20	626.55	220.18	0
105.90	63.00	88.20	582.54	105.90	150.84	154.10	313.28	110.09	0

INNOVATIVE	TRADITIONAL	GENERAL	
151.20	3045.29	0	3196.49
HOG: 0	BG: 0		NA Deprec. 1673.84
			0.00%
			TOTAL 1673.84

APPRAISAL

www.vabfleetservices.be

Date : 11/04/2017

5/5

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min	Towing time : 0 min
	Reason :	Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 11/04/2017 Hour : 14:46	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	