

AQOZ7C

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	38375 KM
File nr. :	1385702	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1KFH045 / WVWZZZ6RZFY115689 /		yr of constructionr :	/
E-File nr. :		First registration :	21/04/2015
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / POLO	Fuel type :	DIESEL
Object nr. :	58825	Fuel :	
Classification :	A	Environment Class:	EURO 6
Customer company :	BIOMEDICAL SYSTEMS SA	Co2:	88g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1422
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Winter tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4 /	Rim :		/	Hubcap : [x] SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :		/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	185	60	R	15	M+S
Rear tyre	185	60	R	15	M+S

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/CENTER	DENT		
[x]	BONNET/CENTER/LEFT	OTHER DAMAGES	OVB POLIEREN	

Interior

[x]	SEAT FL	STAIN		
-----	---------	-------	--	--

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR		169.44 EUR		50 %	169.44 EUR
[x]	REAR WINDOW/RIGHT		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
3	25 LU =120.00 EUR		0 EUR		50 %	120.00 EUR
[x]	REAR DOOR/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR		254.68 EUR		50 %	254.68 EUR
[x]	FRONT DOOR/RIGHT/REAR		OTHER DAMAGES		SLECHTE HERSTELLING	
	Number	Code	Description	Unit price	Depr.	Total
0	0					

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	BACK WINDOW	200.00 EUR	50 %	200.00 EUR

1	2	3	4	5	6	7	8	9	10
169.44	254.68	320.00	0	0	0	0	0	0	0
84.72	127.34	160.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	744.12	0	744.12
HOG: 0	BG: 1		NA Deprec. 372.06
			0.00%
			TOTAL 372.06

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/04/2017 Hour : 11:42 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	