

BM7M3Q

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	76970 KM
File nr. :	1410084	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DKJ070 / WAUZZZ8X6CB242512 /		yr of constructionr :	/
E-File nr. :		First registration :	08/06/2012
VFS-nr. :		Color :	RED
Make + Model :	AUDI / A1	Fuel type :	DIESEL
Object nr. :	46228	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	MAINSYS ENGINEERING SA	Co2:	99g/km
Driver :		Remote controls:	1
Covering :	LEATHER	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	A1 SB Ambition 90PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio :
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 1.6-2/ Rim : [x] WHEEL SCRATCHED / Hubcap : [x] MISSING/INCOMPLETE
Wheel RL : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap : [x] MISSING/INCOMPLETE
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 0-1.6/ Rim : [x] WHEEL SCRATCHED / Hubcap : [x] MISSING/INCOMPLETE
Wheel RR : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap : [x] MISSING/INCOMPLETE
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	45	R	16	V
Rear tyre	215	45	R	16	V

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/LEFT/CENTER	DENT
[x]	REAR DOOR/LEFT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/REAR	DENT
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS

Interior

[x]	BOOT IN L	CARVED
[x]	BOOT IN R	CARVED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	HOLE/CRACK/TORN				
			Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR		0 EUR		50 %	
			Repair paint - LI	New paint - E	Depr.	Total
3	15 LU =72.00 EUR		0 EUR	188.64 EUR	50 %	260.64 EUR
[x]	FRONT DOOR/RIGHT/FRONT	DENT				
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR		176.14 EUR		50 %	176.14 EUR
[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR		169.44 EUR		50 %	169.44 EUR

Accessories and others

[x]	ANTENNA	MISSING/INCOMPLETE			
		Repair paint - LI	New paint - E	Depr.	Total
6	0 LU =0.00 EUR	0 EUR			

Others

RIM FRONT LEFT					
Number	Code	Description	Unit price	Depr.	Total
7	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR
RIM REAR LEFT					
Number	Code	Description	Unit price	Depr.	Total
7	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR
RIM REAR RIGHT					
Number	Code	Description	Unit price	Depr.	Total
7	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR
RIM FRONT RIGHT					
Number	Code	Description	Unit price	Depr.	Total
7	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR
HUB CAP FL					
		Repair paint - LI	New paint - E	Depr.	Total
7	0 LU =0.00 EUR			50 %	
HUB CAP REAR L					
		Repair paint - LI	New paint - E	Depr.	Total
7	0 LU =0.00 EUR			50 %	
HUB CAP REAR RIGHT					
		Repair paint - LI	New paint - E	Depr.	Total
7	0 LU =0.00 EUR			50 %	
HUB CAP FR					
		Repair paint - LI	New paint - E	Depr.	Total
7	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	REAR BUMPER	274.56 EUR	50 %	274.56 EUR
6	1	ANTENNE	12.00 EUR		12.00 EUR
7	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
7	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
7	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
7	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR

1	2	3	4	5	6	7	8	9	10
0	169.44	535.20	63.00	176.14	12.00	476.00	0	0	0
0	84.72	267.60	63.00	88.07	12.00	428.00	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
443.00	988.78	0	1431.78
HOG: 0	BG: 1		NA Deprec. 943.39
			0.00%
			TOTAL 943.39

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 22/06/2017 Hour : 11:19 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	