

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	124852
File nr. :	1414338	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FFL829 / WBA3D91010F405122 /		yr of constructionr :	2013 / 00
E-File nr. :		First registration :	14/06/2013
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / 3	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :	G	Environment Class:	EURO 5
Customer company :	Fujitsu Technology Solutions	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	3 BER 316d 116PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner : [x]	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Winter tires

Wheel FL: [x] GOODYEAR Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] GOODYEAR Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel FR : [x] GOODYEAR Tyre : [x] OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RR : [x] GOODYEAR Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	M+S
Rear tyre	205	60	R	16	M+S

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT		DENT						
		Repair paint - LI	New paint - E		Depr.		Total		
2	15 LU =72.00 EUR	211.80 EUR			50 %		283.80 EUR		
[x]	REAR MUDGUARD/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE						
		Repair paint - LI	New paint - E		Depr.		Total		
4	0 LU =0.00 EUR	308.20 EUR			50 %		308.20 EUR		
[x]	REAR DOOR/LEFT/CENTER		DENT						
	Number	Code	Description		Unit price	Depr.	Total		
1	I 1	i-vab-uitd-01	BEAT OUT DENT		63.00 EUR		63.00 EUR		
[x]	REAR DOOR/RIGHT/CENTER		DENT						
		Repair paint - LI	New paint - E		Depr.		Total		
3	5 LU =24.00 EUR	0 EUR			50 %		24.00 EUR		
	Number	Code	Description		Unit price	Depr.	Total		
3	I 1	i-vab-uitd-01	BEAT OUT DENT		63.00 EUR		63.00 EUR		

1	2	3	4	5	6	7	8	9	10
63.00	283.80	87.00	308.20	0	0	0	0	0	0
63.00	141.90	75.00	154.10	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
126.00	616.00	0	742.00
HOG: 0	BG: 0		NA Deprec. 434.00
			0.00%
			TOTAL 434.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 08/07/2017 Hour : 11:41 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	