

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	148180 KM
File nr. :	1414830	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DOC002 / WBA1C91030J199339 /		yr of constructionr :	/
E-File nr. :		First registration :	04/07/2012
VFS-nr. :		Color :	BLUE
Make + Model :	BMW / 1	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KBC BANK NV	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE-LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	1 HATCH 116d Eff.Dyn.Ed. 116PK	Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:	04/07/2017	Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK [x]	1.6-2/	Rim :	/	Hubcap :
Wheel RL :	[x]	GOODYEAR	Tyre :	OK [x]	1.6-2/	Rim :	/	Hubcap :
Wheel FR :	[x]	GOODYEAR	Tyre :	[x] OK [x]	1.6-2/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK [x]	1.6-2/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	SCRATCH WITH PAINT DAMAGE	POLIR
[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	CHARGEMENT / POLIR
[x]	REAR DOOR/CENTER/LEFT	OTHER DAMAGES	FORMATION ROUILLE SOUS LAQUE
[x]	REAR DOOR/LEFT/FRONT	DENT	
[x]	REAR DOOR/RIGHT/CENTER	DENT	
[x]	REAR DOOR/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT DOOR/LEFT/REAR	DENT	
[x]	WINDSCREEN/CENTER/LEFT	CHIPS	
[x]	FRONT DOOR/RIGHT/REAR	DENT	
[x]	BONNET/CENTER/RIGHT	OTHER DAMAGES	ISOLATION TROUEE
[x]	LIGHTS/LEFT/FRONT	OTHER DAMAGES	JOINT CAPOT/FACE AV FIXER

Interior

[x]	SEAT FR	STAIN
[x]	DOOR IN FL	SCRATCHED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT DOOR/LEFT/CENTER	DENT				
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT BUMPER/LEFT/CORNER	SCRATCH WITH PAINT DAMAGE	SOUS BASSEMENT G/D			
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

1	2	3	4	5	6	7	8	9	10
115.56	63.00	0	0	0	0	0	0	0	0
115.56	63.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
178.56	0	0	178.56
HOG: 0	BG: 0		NA Deprec. 178.56
			0.00%
			TOTAL 178.56

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 05/07/2017 Hour : 14:09 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	