

www.vabfleetservices.be Date: 10/07/2017 1/4

BTT9A7

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage:	183827 KM
File nr. :	1416089	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FIE934 / WBAFW110X0C71	4808 /	yr of constructionr :	/
E-File nr. :		First registration :	04/07/2013
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / 5	Fuel type :	DIESEL
Object nr. :	10412	Fuel :	
Classification:		Environment Class:	EURO 5
Customer company:	SIOEN INDUSTRIES NV	Co2:	125g/km
Driver :		Remote controls:	2
Covering:	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	5 BER 520d Start/Stop 163PK	Country registration :	BELGIUM

		·					
Variant car:	BERLINE	Engine size:	1995				
Gear box :	Manueel	Number of places:	5				
Number of gears:	6	Number of doors:	4				
HP:	163	kW:	120				
Fisc HP		Imported vehicle:					
Animals transported:	No	Smoked in vehicle:	No				
Due date vehicle inspection:		Extra set of tires:					
		Use:	Unknown				
General condition:							

Metallic paint:

Yes



www.vabfleetservices.be Date: 10/07/2017 2/4

Original registr. number: OK Service manual:

Cert. of reg. / Part 1: Cert. of conformity: OK

Cert. of reg. copy / Part 2: OK [x] Insurance certificate :

Warning vest : Transport licence :

Tax certificate: Navigation CD/SD/DVD

Fuel card: Car radio: OK [x]

Mobile phone kit: Extinguisher: OK [x]

Warning triangle : OK [x]

First aid kit: OK [x] Oil level: OK [x]

Jack, wheelspanner: Filled up: 0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/	Hubcap:
Wheel RL:	[x]	CONTINENTAL	Tyre:		OK	[x]	2-4 /	Rim:			/	Hubcap:
Wheel FR:	[x]	CONTINENTAL	Tyre:	[x]	OK	[x]	2-4 /	Rim:			/	Hubcap:
Wheel RR:	[x]	CONTINENTAL	Tyre:		OK	[x]	2-4 /	Rim:			/	Hubcap:
Wheel RES:	[x]		Tyre:		OK		/	Rim ·			/	Hubcan ·

[x]	Width	Height	Туре	Rim	Index
Front tyre	225	55	R	17	Y
Rear tyre	225	55	R	17	Y

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 10/07/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[X] REAR BUMPER/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE)

[x] WINDSCREEN/CENTER/LEFT CHIPS

[x] BONNET/CENTER/RIGHT/FRONT CHIPS

[x] FRONT BUMPER/CENTER/RIGHT CHIPS

	1	2	3	4	5	6	7	8	9	10
	0	0	0	0	0	0	0	0	0	0
Γ	0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	0	0		0
HOG: 0	BG: 2		NA Deprec.	0
			0.00%	
			TOTAL	0



10/07/2017 Date: www.vabfleetservices.be 4/4

[x] = Status Modification

Pictures: No

CIRCUMS	STANCES		UNDER CONDITION - DUSTY VEHICLE				
Extra Time :	0 min	Waiting time: 0 m Reason:	in	Towing time : Reason :	0 min		
NOT EXECUTED Reason:	: No	L					
Remark:							
Prices in EUR	without VAT						
Authorized by customer:			Executed by VAB Fleet S	Services			
Remark authorized	d customer :						
Date :	10/07/2017	Hour: 08:02					
Company :							
Executed by VAB l Services	Fleet						
E-Mail :	@						
Signature authorized	l by customer						
/							