

www.vabfleetservices.be Date: 13/07/2017 1/4

BVE7XO

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	161373 KM
File nr. :	1417278	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FWB816 / WBA5J11010D06	5257 /	yr of constructionr :	/
E-File nr. :		First registration :	14/11/2013
VFS-nr. :		Color :	BROWN D
Make + Model :	BMW / 5 TOURING	Fuel type :	DIESEL
Object nr. :	6079	Fuel:	
Classification:	L	Environment Class:	EURO 5
Customer company :	COMPASS GROUP NV	Co2:	129g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	5 TOURING 518dA 136PK Aut.	Country registration :	BELGIUM

_		_	
Variant car:	BREAK	Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
нр:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Metallic paint:

Yes



www.vabfleetservices.be Date: 13/07/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Winter tires

Wheel FL:	[x]	BRIDGESTONE	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:	
Wheel RL:	[x]	BRIDGESTONE	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:	
Wheel FR:	[x]	BRIDGESTONE	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:	
Wheel RR:	[x]	BRIDGESTONE	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:	
Wheel RES:	[x]		Tyre:		OK		/	Rim:			/ Hubcap:	
		[x] W	/idth			H	eight	1		Type	Rim	Index

	[x]	Width	Height	Type	Rim	Index
Fro	nt tyre	225	55	R	17	M+S
Rea	ar tyre	225	55	R	17	M+S

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 13/07/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] REAR DOOR/RIGHT/REAR DENT

STATUS: NOT ACCEPTABLE

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

 Repair paint - LI
 New paint - E
 Depr.
 Total

 1 0 LU = 0.00 EUR
 254.16 EUR
 50 %
 254.16 EUR

Others

RIM FRONT LEFT

	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
254.16	190.00	0	0	0	0	0	0	0	0
127.08	190.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
190.00	254.16	0		444.16
HOG: 0	BG: 2		NA Deprec.	317.08
			0.00%	
			TOTAL	317.08



www.vabfleetservices.be Date: 13/07/2017 4/4

[x] = Status Modification

TANCES					
	NORMAL CONCLUSION				
0 min	Waiting time: 0 min Reason:		Towing time : Reason :	0 min	
No	I				
ithout VAT					
		Executed by VAB Flee	et Services		
ustomer :					
13/07/2017	Hour: 06:45				
not.					
Ci					
@					
y customer					
	No ithout VAT ustomer: 13/07/2017 eet @	No No	Reason: No Sthout VAT Executed by VAB Flee 13/07/2017 Hour: 06:45	Reason: No Sthout VAT Executed by VAB Fleet Services 13/07/2017 Hour: 06:45 et @	No Reason : Reason :