

www.vabfleetservices.be Date: 25/07/2017 1/5

BZSCY3

[X] EFFECTIVE [] NOT EXECUTED

[X] COLLECTION

[] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 113404 KM File nr. : Mileage start / arrival: 0 / 01420696 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1DQR302 / TRUZZZ8P0D1000928 / E-File nr. : First registration: 25/07/2012 Color: VFS-nr.: **GREY** Make + Model : Fuel type : AUDI / A3 CABRIO **DIESEL** Object nr. : Fuel: Classification: **Environment Class:** EURO 5 Customer company: Co2: KBC VERZEKERINGEN NV 114g/km Driver : Remote controls: 2 LEATHER Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 4 [x] A3 CABRIO Ambition Start/Stop DPF 105PK Vehicle type: Country registration: **BELGIUM**

VAT over the margin - car:		Metallic paint:	Yes			
Variant car:	CABRIOLET	Engine size:	1598			
Gear box :	Manueel	Number of places:	4			
Number of gears:	5	Number of doors:	2			
HP:	105	kW:	77			
Fisc HP		Imported vehicle:				
Animals transported:		Smoked in vehicle:	No			
Due date vehicle inspection:	25/07/2018	Extra set of tires:	No			
		Use:	Unknown			
General condition:						



www.vabfleetservices.be Date: 25/07/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :			Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Rea	r tyre		225			4	45		R 17		17	W	
From	nt tyre		225			4	45			R		17	W
		[x]	Width			He	eight			Type		Rim	Index
Wheel RES:	[x]		Tyre:		OK		/	Rim:				/ Hubcap:	
Wheel RR:	[x]	PIRELLI	Tyre:		OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel FR:	[x]	GOODYEAR	Tyre:	[x]	OK	[x]	4-6 /	Rim:	[x]	E] WHEEL SCRATCHED / Hubcap:			
Wheel RL:	[x]	PIRELLI	Tyre:		OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED / Hubcap:		/ Hubcap:	
Wheel FL:	[x]	GOODYEAR	Tyre :		OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:

Remark:



2 15 LU =72.00 EUR

APPRAISAL

www.vabfleetservices.be Date: 25/07/2017 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

Boo	dywork \& windows							
x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE	L/R				
x]	REAR MUDGUARD/LEFT/FRONT		DENT	DENT				
c]	REAR WINDOW/LEFT		STICKER(S)					
x]	REAR MUDGUARD/RIGHT/CENTER		DENT					
κ]	FRONT DOOR/LEFT/REAR		SCRATCH WITH PAINT DAMAGE	BOORD DEUR				
x]	FRONT DOOR/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE	BOORD DEUR				
x]	FRONT MUDGUARD/RIGHT/FRONT		CHIPS					
x]	FRONT BUMPER/RIGHT		SCRATCH WITH PAINT DAMAGE					
nte	erior							
x]	FLOOR FL		HOLE					
k]	DOOR IN FL		SCRATCHED					
x]	BOOT LID IN		SCRATCHED					
\cc	essories and others							
x]	OUTSIDE MIRROR LEFTHAND SIDE		SCRATCH WITH PAINT DAMAGE					
x]	OUTSIDE MIRROR RIGHTHAND SIDE		SCRATCH WITH PAINT DAMAGE					
ST	ATUS: NOT ACCEPTAB	LE						
300	dywork \& windows							
x]	WINDSCREEN/CENTER/LEFT		WINDOW DAMAGE					
		Repair paint - LI	New paint - E	Depr.	Total			
	1 0 LU =0.00 EUR	0 EUR		50 %				
		Repair paint - LI	New paint - E	Depr.	Total			
	1 25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR			
x]	FRONT THRESHOLD/RIGHT/REAR		DENT	EXT				
		Repair paint - LI	New paint - E	Depr.	Total			

320.40 EUR

50 %

248.40 EUR



www.vabfleetservices.be Date: 25/07/2017 4/5

	www.vabileciscivices.pc									
Ot	Others									
	RIM FRONT LEFT									
	Number	Code		Description			Unit pr	ice Depr		Total
	3 I1	i-vab-herstalu-02		REPAIR AL	LOY WHEEL		95.00 E	UR	1	95.00 EUR
	RIM REA	R LEFT								
	Number	Code		Description			Unit pr	ice Depr		Total
	3 I 1	i-vab-herstalu-02		REPAIR AL	LOY WHEEL		95.00 E	95.00 EUR		
Pie	eces									
	Number	Code		Description			Unit pr	•	Total	
	1 1	WIND SCREEN					293.761		293.76 EUR	
	1	2	3	4	5	6	7	8	9	10
	413.76	320.40	190.00	0	0	0	0	0	0	0
	206.88	160.20	190.00	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
924.16		0	734.16	190.00
557.08	NA Deprec.		BG: 1	HOG: 0
	0.00%			
557.08	TOTAL			



www.vabfleetservices.be Date: 25/07/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMS	STANCES		UNDER (UNDER CONDITION - VEHICLE WET				
Extra Time :	0 min	Waiting time: 0 r Reason:	nin	Towing time : Reason :	0 min			
NOT EXECUTED Reason:	No No	<u> </u>		I				
Remark:								
Prices in EUR	without VAT							
Authorized by customer:	rized by ner :			AB Fleet Services				
Remark authorized	d customer :							
Date :	25/07/2017	Hour: 17:02						
Company: Executed by VAB Services	Fleet							
E-Mail :	@							
Signature authorized	d by customer							