

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|-----------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 152402 KM |
| File nr. : | 1421163 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1GRS186 / WBA3K91040F934439 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 10/04/2014 |
| VFS-nr. : | | Color : | GREY |
| Make + Model : | BMW / 3 TOURING | Fuel type : | |
| Object nr. : | 48590 | Fuel : | |
| Classification : | F | Environment Class: | EURO 5 |
| Customer company : | ROGERS BVBA | Co2: | 123g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | | Metallic paint: | Yes |
| Variant car: | BREAK | Engine size: | 1995 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 116 | kW: | 85 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | | Smoked in vehicle: | |
| Due date vehicle inspection: | | Extra set of tires: | |
| | | Use: | Unknown |
| General condition: | | | |

| | | | |
|------------------------------|--------|-------------------------|--------|
| Original registr. number : | OK | Service manual : | |
| Cert. of reg. / Part 1: | OK [x] | Cert. of conformity : | OK |
| Cert. of reg. copy / Part 2: | | Insurance certificate : | |
| Warning vest : | OK [x] | Transport licence : | |
| Tax certificate : | | Navigation CD/SD/DVD | |
| Fuel card : | | Car radio : | |
| Mobile phone kit : | | Extinguisher : | OK [x] |
| First aid kit : | OK [x] | Warning triangle : | OK [x] |
| Jack, wheelspanner : | | Oil level : | OK [x] |
| | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | | |
|------------|-----|-------------|--------|-----|-----|--------|--------|-------|-----------------|------------|
| Wheel FL: | [x] | BRIDGESTONE | Tyre : | OK | [x] | 1.6-2/ | Rim : | | / | Hubcap : |
| Wheel RL : | [x] | BRIDGESTONE | Tyre : | OK | [x] | 2-4/ | Rim : | [x] | WHEEL SCRATCHED | / Hubcap : |
| Wheel FR : | [x] | BRIDGESTONE | Tyre : | [x] | OK | [x] | 1.6-2/ | Rim : | | / Hubcap : |
| Wheel RR : | [x] | BRIDGESTONE | Tyre : | OK | [x] | 2-4/ | Rim : | | / | Hubcap : |
| Wheel RES: | [x] | | Tyre : | OK | | / | Rim : | | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225 | 50 | R | 17 | Y |
| Rear tyre | 225 | 50 | R | 17 | Y |

Remark :

Wheels and tyres:

| | | | | | | | | |
|------------|--|--------|----|---|-------|--|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | | | |
|-----|------------------------|---------------------------|----|--|
| [x] | ROOF/REAR/RIGHT | DENT | | |
| [x] | FRONT DOOR/LEFT/REAR | SCRATCH WITH PAINT DAMAGE | | |
| [x] | FRONT DOOR/RIGHT/FRONT | DENT | X2 | |
| [x] | BONNET/CENTER/LEFT | DENT | | |

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | | | |
|-----|--------------------------|---------------------------|----------------------|-------------------|--------------|--------------|
| [x] | REAR BUMPER/RIGHT/CORNER | SCRATCH WITH PAINT DAMAGE | | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total | |
| 4 | 0 LU =0.00 EUR | 211.80 EUR | | 50 % | 211.80 EUR | |
| [x] | WINDSCREEN/BELOW/LEFT | WINDOW DAMAGE | | | | |
| | Number | Code | Description | Unit price | Depr. | Total |
| 3 | I 1 | i-vab-herstr-01 | WINDOW REPAIR | 58.80 EUR | | 58.80 EUR |
| [x] | FRONT BUMPER/LEFT/SIDE | SCRATCH WITH PAINT DAMAGE | | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total | |
| 2 | 0 LU =0.00 EUR | 211.80 EUR | | 50 % | 211.80 EUR | |

Others

RIM REAR LEFT

| | | | | | | |
|---|---------------|-------------------|--------------------|-------------------|--------------|--------------|
| | Number | Code | Description | Unit price | Depr. | Total |
| 5 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR |

| | | | | | | | | | |
|----------|----------|----------|----------|----------|----------|----------|----------|----------|-----------|
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
| 0 | 211.80 | 58.80 | 211.80 | 95.00 | 0 | 0 | 0 | 0 | 0 |
| 0 | 105.90 | 58.80 | 105.90 | 95.00 | 0 | 0 | 0 | 0 | 0 |

| | | | |
|-------------------|--------------------|----------------|--------------------------|
| INNOVATIVE | TRADITIONAL | GENERAL | |
| 153.80 | 423.60 | 0 | 577.40 |
| HOG: 0 | BG: 0 | | NA Deprec. 365.60 |
| | | | 0.00% |
| | | | TOTAL 365.60 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---------------------------|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No | | |
| Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 24/07/2017 Hour : 14:21 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |