

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	149322 KM
<b>File nr. :</b>	1414029	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FVE420 / WBA5C110X0D033501 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	05/11/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	BMW / 5	<b>Fuel type :</b>	
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>	L	<b>Environment Class:</b>	EURO 6
<b>Customer company :</b>	OLEON NV	<b>Co2:</b>	119g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BERLINE	<b>Engine size:</b>	1995
<b>Gear box :</b>		<b>Number of places:</b>	5
<b>Number of gears:</b>		<b>Number of doors:</b>	4
<b>HP:</b>	143	<b>kW:</b>	105
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	HANGKOOK	Tyre :	OK	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	4-6/	Rim :			/	Hubcap :
Wheel FR :	[x]	HANGKOOK	Tyre :	OK	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	4-6/	Rim :			/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :			/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	W
Rear tyre	225	55	R	17	W

Remark : REPSET OK

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE	HERSTELLING

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE	DEUK	
		Repair paint - LI	New paint - E	Depr.
1	0 LU =0.00 EUR	254.16 EUR		50 %
				Total
				254.16 EUR

### Others

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
254.16	95.00	0	0	0	0	0	0	0	0
127.08	95.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	254.16	0	349.16
HOG: 0	BG: 2		NA Deprec. 222.08
			0.00%
			TOTAL 222.08

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b> SCHADE BUMPER VOOR WAS NIET OPGENOMEN IN VORIG BESTEK, GEBELD AAN HR  <b>Date :</b> 03/07/2017 <b>Hour :</b> 13:37  <b>Company :</b>  <b>Executed by VAB Fleet Services</b> <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	