

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	25069 KM
File nr. :	1421790	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1KJK444 / WBAWZ310100F65065 /		yr of constructionr :	/
E-File nr. :		First registration :	12/05/2015
VFS-nr. :		Color :	RED
Make + Model :	BMW / X3	Fuel type :	DIESEL
Object nr. :	46163	Fuel :	
Classification :		Environment Class:	EURO 6
Customer company :	ANSELL HEALTHCARE EUROPE SA	Co2:	130g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	NOK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	DUNLOP	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	DUNLOP	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	DUNLOP	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	DUNLOP	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	60	R	17	V
Rear tyre	225	60	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/CORNER		SCRATCH WITH PAINT DAMAGE	+DEUK					
		Repair paint - LI	New paint - E		Depr.		Total		
2	0 LU =0.00 EUR	211.80 EUR			50 %		211.80 EUR		
[x]	REAR DOOR/LEFT/FRONT		DENT		2X				
	Number	Code	Description		Unit price	Depr.		Total	
1	I 1	i-vab-uitd-01	BEAT OUT DENT		63.00 EUR			63.00 EUR	
	Number	Code	Description		Unit price	Depr.		Total	
1	I 1	i-vab-uitd-02	BEAT OUT DENT SUPPL		19.80 EUR			19.80 EUR	
[x]	FRONT DOOR/RIGHT/REAR		DENT						
		Repair paint - LI	New paint - E		Depr.		Total		
3	0 LU =0.00 EUR	318.35 EUR			50 %		318.35 EUR		
[x]	ROOF/CENTER/LEFT		OTHER DAMAGES		CHEMISCHE INWERKING				
		Repair paint - LI	New paint - E		Depr.		Total		
4	0 LU =0.00 EUR	481.50 EUR			50 %		481.50 EUR		

1	2	3	4	5	6	7	8	9	10
82.80	211.80	318.35	481.50	0	0	0	0	0	0
82.80	105.90	159.18	240.75	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
82.80	1011.65	0	1094.45
HOG: 0	BG: 0		NA Deprec. 588.62
			0.00%
			TOTAL 588.62

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/07/2017 Hour : 10:13 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	