

CONCCK

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	58047 KM
File nr. :	1421390	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EZF308 / WDD1760121J101301 /		yr of constructionr :	/
E-File nr. :		First registration :	26/04/2013
VFS-nr. :		Color :	BLACK
Make + Model :	MERCEDES / A	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :	N	Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	98g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	109	kW:	80
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK
Cert. of reg. / Part 1: OK	Cert. of conformity : OK
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK
Mobile phone kit :	Extinguisher : OK
First aid kit : OK	Warning triangle : OK
Jack, wheelspanner :	Oil level : OK
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL:	CONTINENTAL	Tyre :	OK	2-4/	Rim :	[x] WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	CONTINENTAL	Tyre :	OK	2-4/	Rim :		/	Hubcap :
Wheel FR :	CONTINENTAL	Tyre :	OK	2-4/	Rim :		/	Hubcap :
Wheel RR :	CONTINENTAL	Tyre :	OK	2-4/	Rim :		/	Hubcap :
Wheel RES:	ANDERE	Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR DOOR/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	ROOF/CENTER/RIGHT	DENT	
[x]	REAR DOOR/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	DEURRAND
[x]	FRONT DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE	ONDER

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	DENT	+ LAKSCHADE
		Repair paint - LI	New paint - E
			Depr.
			Total
1	0 LU =0.00 EUR	211.80 EUR	50 %
			211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	0	0	0	0	0	0	0	0	0
105.90	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	211.80	0	211.80
HOG: 0	BG: 0		NA Deprec. 105.90
			0.00%
			TOTAL 105.90

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK // REGEN [x]		

Prices in EUR without VAT

<p>Authorized by customer : I KNOW THE STATE OF THE VEHICLE AND I AGREE WITH THE REPORT AND ITS ATTACHMENTS;</p> <p>Remark authorized customer :</p> <p>Date : 20/07/2017 Hour : 16:49</p> <p>Company :</p> <p>Executed by VAB Fleet Services</p> <p>E-Mail : @</p>	<p>Executed by VAB Fleet Services</p>
<p>Signature authorized by customer</p> 	