

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	32136 KM
File nr. :	1421317	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1BAW054 / WFOXXXTTFXBD72390 /		yr of constructionr :	/
E-File nr. :		First registration :	20/04/2011
VFS-nr. :		Color :	BLUE D
Make + Model :	FORD / TRANSIT	Fuel type :	DIESEL
Object nr. :	46115	Fuel :	
Classification :		Environment Class:	EURO 4
Customer company :	GEMEENTE ETTERBEEK	Co2:	222g/km
Driver :		Remote controls:	1
Covering :	IMITATION LEATHER	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	TRANSIT B/F 280M MWB Ambiente DPF 85PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	BESTELWAGEN	Engine size:	2198
Gear box :	Manueel	Number of places:	3
Number of gears:	5	Number of doors:	5
HP:	86	kW:	63
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	MISSING/INCOMPLETE	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	195	70	R	15	R
Rear tyre	195	70	R	15	R

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT		HOLE/CRACK/TORN				
		Repair paint - LI	New paint - E	Depr.	Total		
5	15 LU =72.00 EUR	0 EUR		50 %	72.00 EUR		
[x]	REAR MUDGUARD/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total		
4	0 LU =0.00 EUR	193.71 EUR		50 %	193.71 EUR		
[x]	REAR MUDGUARD/LEFT/FRONT		SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total		
3	0 LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR		
[x]	REAR MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total		
6	0 LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR		
[x]	REAR THRESHOLD/LEFT/REAR		SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total		
3	0 LU =0.00 EUR	232.88 EUR		50 %	232.88 EUR		
[x]	REAR DOOR/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total		
3	0 LU =0.00 EUR	238.76 EUR		50 %	238.76 EUR		
[x]	ROOF STYLE/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total		
7	0 LU =0.00 EUR	165.14 EUR		50 %	165.14 EUR		
[x]	REAR DOOR/RIGHT/REAR		DENT				
		Repair paint - LI	New paint - E	Depr.	Total		
6	0 LU =0.00 EUR	238.76 EUR		50 %	238.76 EUR		
[x]	FRONT DOOR/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total		
3	0 LU =0.00 EUR	238.76 EUR		50 %	238.76 EUR		

[x]	ROOF /FRONT/LEFT/CENTER		DENT		
		Repair paint - LI	New paint - E	Depr.	Total
8	0 LU =0.00 EUR	361.13 EUR		50 %	361.13 EUR
[x]	FRONT DOOR/RIGHT/REAR		DENT		
		Repair paint - LI	New paint - E	Depr.	Total
6	0 LU =0.00 EUR	238.76 EUR		50 %	238.76 EUR
[x]	FRONT MUDGUARD/LEFT/FRONT		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	165.13 EUR		50 %	165.13 EUR
[x]	BONNET/CENTER/RIGHT		OTHER DAMAGES	CHEM INW	
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	217.56 EUR		50 %	217.56 EUR
[x]	FRONT MUDGUARD/RIGHT/FRONT		DENT		
		Repair paint - LI	New paint - E	Depr.	Total
6	0 LU =0.00 EUR	165.13 EUR		50 %	165.13 EUR
[x]	FRONT BUMPER/CENTER/RIGHT		HOLE/CRACK/TORN		
		Repair paint - LI	New paint - E	Depr.	Total
1	20 LU =96.00 EUR	0 EUR		50 %	96.00 EUR

Others

	HUB CAP FL				
		Repair paint - LI	New paint - E	Depr.	Total
9	0 LU =0.00 EUR			50 %	
	HUB CAP REAR L				
		Repair paint - LI	New paint - E	Depr.	Total
9	0 LU =0.00 EUR			50 %	
	HUB CAP REAR RIGHT				
		Repair paint - LI	New paint - E	Depr.	Total
9	0 LU =0.00 EUR			50 %	
	HUB CAP FR				
		Repair paint - LI	New paint - E	Depr.	Total
9	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	FRONT BUMPER	302.40 EUR	50 %	302.40 EUR
5	1	REAR BUMPER	257.40 EUR	50 %	257.40 EUR
9	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
9	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
9	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
9	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR

1	2	3	4	5	6	7	8	9	10
398.40	217.56	1106.68	193.71	329.40	873.80	165.14	361.13	90.00	0
199.20	108.78	553.34	96.86	164.70	436.90	82.57	180.56	45.00	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	3735.82	0	3735.82
HOG: 0	BG: 3		NA Deprec. 1867.91
			0.00%
			TOTAL 1867.91

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 27/07/2017 Hour : 10:58 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	