

C1X7Y4

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	82200 KM
<b>File nr. :</b>	1422390	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1BGM415 / VF1FDA2D640162151 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	21/08/2008
<b>VFS-nr. :</b>		<b>Color :</b>	WHITE
<b>Make + Model :</b>	RENAULT / MASTER	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	12509	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 4
<b>Customer company :</b>	MIVB-STIB OI	<b>Co2:</b>	g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	0
<b>Vehicle kind :</b>	TRUCK, LORRY	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	MASTER 28 B/F SWB L1H1 Conf.101pk	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	No
<b>Variant car:</b>	BESTELWAGEN	<b>Engine size:</b>	2464
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	3
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	101	<b>kW:</b>	74
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :		Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	NOK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	ANDERE	Tyre :	OK [x]	0-1.6/	Rim :	[x]	BROKEN DOWN / DAMAGED /	Hubcap :
Wheel RL :	[x]	ANDERE	Tyre :	OK [x]	0-1.6/	Rim :			Hubcap :
Wheel FR :	[x]	ANDERE	Tyre :	[x] OK [x]	2-4/	Rim :	[x]	BROKEN DOWN / DAMAGED /	Hubcap :
Wheel RR :	[x]	ANDERE	Tyre :	OK [x]	2-4/	Rim :			Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :			Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	16	H
Rear tyre	195	65	R	16	H

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK /	Rim :		Hubcap :
Wheel RL :		Tyre :	OK /	Rim :		Hubcap :
Wheel FR :		Tyre :	OK /	Rim :		Hubcap :
Wheel RR :		Tyre :	OK /	Rim :		Hubcap :
Wheel RES:		Tyre :	OK /	Rim :		Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR DOOR/LEFT/CENTER	DENT
[x]	FRONT BUMPER/LEFT/CORNER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT BUMPER/RIGHT/CORNER	SCRATCH (WITHOUT PAINT DAMAGE)

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR LIGHT/LEFT/CORNER	HOLE/CRACK/TORN	
		<b>Repair paint - LI      New paint - E      Depr.      Total</b>	
3	5 LU =24.00 EUR	0 EUR	50 %      24.00 EUR
[x]	REAR BUMPER/CENTER/LEFT	DENT	
		<b>Repair paint - LI      New paint - E      Depr.      Total</b>	
4	15 LU =72.00 EUR	0 EUR	50 %      72.00 EUR
[x]	ROOF/CENTER/LEFT	OTHER DAMAGES	
		<b>Repair paint - LI      New paint - E      Depr.      Total</b>	
2	5 LU =24.00 EUR	0 EUR	50 %      24.00 EUR
[x]	FRONT THRESHOLD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	
		<b>Repair paint - LI      New paint - E      Depr.      Total</b>	
5	10 LU =48.00 EUR	232.88 EUR	50 %      280.88 EUR
[x]	FRONT MUDGUARD/RIGHT/FRONT	DENT	
		<b>Repair paint - LI      New paint - E      Depr.      Total</b>	
7	0 LU =0.00 EUR	165.13 EUR	50 %      165.13 EUR

### Interior

[x]	DASHBOARD	MISSING/INCOMPLETE	
		<b>Repair paint - LI      New paint - E      Depr.      Total</b>	
1	5 LU =24.00 EUR	0 EUR	50 %      24.00 EUR
[x]	SEAT FR	CUT / TORN	
		<b>Number   Code      Description      Unit price      Depr.      Total</b>	
1	I 1      i-vab-intvlr-01	VELOURS REPAIR (MAX 3CM LENGTH OR DIAMATER)	64.32 EUR           64.32 EUR

[x]	DOOR IN FL		CUT / TORN		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

### Others

RIM FRONT LEFT

		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
6	5 LU =24.00 EUR			50 %	24.00 EUR

RIM FRONT RIGHT

		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
6	5 LU =24.00 EUR			50 %	24.00 EUR

### Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	OPSTAP	45.00 EUR	50 %	45.00 EUR
1	2	OPBERGVAK	20.00 EUR	50 %	40.00 EUR
2	1	ZWAAILAMP	50.00 EUR	50 %	50.00 EUR
3	1	REAR LIGHT	67.50 EUR	50 %	67.50 EUR
4	1	REAR BUMPER	257.40 EUR	50 %	257.40 EUR
6	1	STEEL WHEEL	48.60 EUR	50 %	48.60 EUR
6	1	STEEL WHEEL	48.60 EUR	50 %	48.60 EUR

1	2	3	4	5	6	7	8	9	10
197.32	74.00	91.50	329.40	280.88	145.20	165.13	0	0	0
130.82	37.00	45.75	164.70	140.44	72.60	82.56	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
64.32	1219.11	0	<b>1283.43</b>
HOG: 0	BG: 3		NA Deprec. 673.88
			0.00%
			<b>TOTAL 673.88</b>



[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b> 2e SLEUTEL IS NIET GECODEERD [x]		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 27/07/2017 <b>Hour :</b> 11:00 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	