

C0K6R1

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	44697 KM
File nr. :	1421322	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ERM217 / WVVZZZAUZDW095115 /		yr of constructionr :	/
E-File nr. :		First registration :	01/03/2013
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :	70160	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ESCENT SA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	GOLF BER Highline 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	[x]
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	4-6/	Rim :		Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	4-6/	Rim :		Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	OK	4-6/	Rim :		Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	4-6/	Rim :	WHEEL SCRATCHED	Hubcap :
Wheel RES:	[x]		Tyre :	OK	2-4/	Rim :		Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/CENTER/LEFT	DENT	
[x]	REAR DOOR/RIGHT/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)	OVBH POL.
[x]	REAR DOOR/LEFT/CENTER	DENT	2X
[x]	ROOF/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)	POLIEREN
[x]	REAR DOOR/RIGHT/FRONT	DENT	
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT DOOR/RIGHT/FRONT	DENT	
[x]	FRONT MUDGUARD/RIGHT/REAR	DENT	
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS	

Interior

[x]	ROOF UPHOLSTERY	MISSING/INCOMPLETE
-----	-----------------	--------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/FRONT	DENT				
	Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	REAR DOOR/LEFT/FRONT	DENT				
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE			MEERDERE KRASSEN	
		Repair paint - LI	New paint - E		Depr.	Total
1	0 LU =0.00 EUR	211.80 EUR			50 %	211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	63.00	63.00	0	0	0	0	0	0	0
105.90	63.00	63.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
126.00	211.80	0	337.80
HOG: 0	BG: 0		NA Deprec. 231.90
			0.00%
			TOTAL 231.90

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 25/07/2017 Hour : 11:45 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	