

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	123247 KM
File nr. :	1418686	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EVP450 / YV1MV8481D2050176 /		yr of constructionr :	/
E-File nr. :		First registration :	02/04/2013
VFS-nr. :		Color :	
Make + Model :	VOLVO / V40	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	94g/km
Driver :		Remote controls:	
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	V40 D2 Base 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]	ANDERE	Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	WINDSCREEN/CENTER/LEFT	CHIPS
[x]	BONNET/CENTER/LEFT	CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE	
		Repair paint - LI New paint - E Depr. Total	
2	0 LU =0.00 EUR	211.80 EUR	50 % 211.80 EUR
[x]	REAR BUMPER/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE	
		Repair paint - LI New paint - E Depr. Total	
2	0 LU =0.00 EUR	0 EUR	
[x]	REAR WINDOW/LEFT	SCRATCH WITH PAINT DAMAGE	
		Repair paint - LI New paint - E Depr. Total	
3	25 LU =120.00 EUR	0 EUR	50 % 120.00 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE	
		Repair paint - LI New paint - E Depr. Total	
3	0 LU =0.00 EUR	308.20 EUR	308.20 EUR
[x]	WINDOW REAR DOOR/LEFT	WINDOW DAMAGE	
		Repair paint - LI New paint - E Depr. Total	
4	20 LU =96.00 EUR	0 EUR	50 % 96.00 EUR
[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	
		Repair paint - LI New paint - E Depr. Total	
3	0 LU =0.00 EUR	318.35 EUR	50 % 318.35 EUR
[x]	WINDOW REAR DOOR/RIGHT	WINDOW DAMAGE	
		Repair paint - LI New paint - E Depr. Total	
4	20 LU =96.00 EUR	0 EUR	50 % 96.00 EUR

[x]	WINDOW FRONT DOOR/RIGHT		WINDOW DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total	
4	20 LU =96.00 EUR	0 EUR		50 %	96.00 EUR	
[x]	FRONT BUMPER/LEFT		DENT			
		Repair paint - LI	New paint - E	Depr.	Total	
1	25 LU =120.00 EUR	0 EUR	235.80 EUR	50 %	355.80 EUR	
[x]	FRONT BUMPER/RIGHT		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total	
1	0 LU =0.00 EUR	0 EUR				
[x]	WINDOW FRONT DOOR/LEFT		WINDOW DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total	
4	20 LU =96.00 EUR	0 EUR		50 %	96.00 EUR	

Interior

[x]	FLOOR FL		HOLE			
	Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-inttap-01	CARPET REPAIR (MAX 3CM LENGTH OR DIAMETER)	43.92 EUR		43.92 EUR

Others

RIM FRONT LEFT

	Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

	Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	FRONT BUMPER	403.20 EUR	50 %	403.20 EUR
4	1	ZIJRUIT	150.00 EUR	50 %	150.00 EUR
4	1	ZIJRUIT	150.00 EUR	50 %	150.00 EUR
4	1	ZIJRUIT	150.00 EUR	50 %	150.00 EUR
4	1	ZIJRUIT	150.00 EUR	50 %	150.00 EUR
3	1	BACK WINDOW	250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
759.00	211.80	996.55	984.00	190.00	43.92	0	0	0	0
379.50	105.90	652.38	492.00	190.00	43.92	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
233.92	2951.35	0	3185.27
HOG: 0	BG: 0		NA Deprec. 1863.70
			0.00%
			TOTAL 1863.70

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/07/2017 Hour : 10:59 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	