

COLWOR

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	182575 KM
File nr. :	1421364	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ECL896 / YV1BW84A1D1261017 /		yr of constructionr :	/
E-File nr. :		First registration :	19/10/2012
VFS-nr. :		Color :	BROWN
Make + Model :	VOLVO / V70	Fuel type :	DIESEL
Object nr. :	51411	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	CEGEKA NV	Co2:	119g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	0
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	V70 D2 Kinetic St/St 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK
Mobile phone kit :	Extinguisher : OK
First aid kit : OK	Warning triangle : OK
Jack, wheelspanner : OK	Oil level : OK
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL:	UNIROYAL	Tyre :	OK	>6/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	UNIROYAL	Tyre :	OK	>6/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	UNIROYAL	Tyre :	OK	>6/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	UNIROYAL	Tyre :	OK	>6/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	245	45	R	17	Y
Rear tyre	245	45	R	17	Y

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR WINDOW STYLE/CENTER/LEFT/UP	SCRATCH (WITHOUT PAINT DAMAGE)	OVB POLIEREN
[x]	REAR DOOR/LEFT/REAR	DENT	
[x]	ROOF/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	OVB POLIEREN
[x]	BONNET/RIGHT/CENTER	DENT	MET LAKSCHADE

Interior

SEAT FL	CARVED
BOOT LID IN	SCRATCHED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

Others

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
254.16	190.00	0	0	0	0	0	0	0	0
127.08	190.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
190.00	254.16	0	444.16
HOG: 0	BG: 2		NA Deprec. 317.08
			0.00%
			TOTAL 317.08

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 20/07/2017 Hour : 12:38 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	