

### **APPRAISAL**

www.vabfleetservices.be

Date : 26/07/2017

1/4

C14A7O

### [X] EFFECTIVE [] NOT EXECUTED

[X] COLLECTION

[] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	142677 KM
File nr. :	1421801	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DLP923 / YV1FW84A1D109	94447 /	yr of constructionr :	/
E-File nr. :		First registration :	18/06/2012
VFS-nr. :		Color :	BLACK
Make + Model :	VOLVO / V60	Fuel type :	DIESEL
Object nr. :	34314	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BARCO NV	Co2:	119g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	V60 D2 Kinetic St/St 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:		1	



## **APPRAISAL**

www.vabfleetservices.be

Date : 26/07/2017

Original registr. number : OK Service manual : OK [x] Cert. of conformity : Cert. of reg. / Part 1: OK Insurance certificate : Cert. of reg. copy / Part 2: OK [x] Transport licence : Warning vest : OK [x] Tax certificate : Navigation CD/SD/DVD Fuel card : Car radio : Extinguisher : Mobile phone kit : OK [x] Warning triangle : OK [x] First aid kit : ОК Oil level : OK [x] [x] Filled up : 0 Jack, wheelspanner :

#### Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :		OK	[x]	2-4 /	Rim :			/ Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :		OK	[x]	2-4 /	Rim :			/ Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	ОК	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :	
Wheel RR :	[x]	MICHELIN	Tyre :		ОК	[x]	2-4 /	Rim :			/ Hubcap :	
Wheel RES:	[x]		Tyre :		ОК		/	Rim :			/ Hubcap :	
		[x]	Width			He	ight			Туре	Rim	Index
From	t tyre		205		60					R	16	V
Door	r tyre		205		60			R	16	V		

#### Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/ Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/ Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/ Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/ Hubcap :
	-				-
Wheel RES:	Tyre :	OK	/	Rim :	/ Hubcap :
	e e				1

Front tyre00R0Bear tyre00R0	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
Keartyre 0 0 K 0	Rear tyre	0	0	R	0	

Remark :

2/4



### **APPRAISAL**

www.vabfleetservices.be

Date : 26/07/2017

TOTAL

#### **STATUS: ACCEPTABLE / USAGE DAMAGE**

	dywork <sup>v</sup>	& window	/S								
[x]	REAR DO	OR/LEFT/FRON	ΙT			DENT					
[x]	REAR DO	OR/RIGHT/CEN	ITER			SCRATCH (WITHOUT PAINT DAMAGE)					
x]	FRONT D	OOR/LEFT/REA	ıR			SCRATCH WITH I	PAINT DAMAGI	Ξ			
x]	FRONT D	OOR/RIGHT/CE	ENTER			SCRATCH (WITH	OUT PAINT DAI	MAGE)			
x]	BONNET/	30NNET/CENTER/LEFT/FRONT									
[x]	FRONT B	UMPER/CENTE	R/LEFT			SCRATCH WITH I	PAINT DAMAGI	Ξ			
Ac	cessorie	s and oth	ers								
[x]	DOORHA	NDLE				SCRATCH WITH I	PAINT DAMAGI	Ξ			
ет	ATUC.										
וכ	A105:	NUTAC	CEPTAB								
Bo	dywork <sup>v</sup>	& window	/S								
[x]	REAR BU	MPER/CENTER	/LEFT			SCRATCH WITH PAINT DAMAGE					
						New paint - E Depr. Total					
	<b>3</b> 0 LU =0.00 EUR 211.80 EUR					New paint - E		Depr.		Total	
	<b>3</b> 0 LU =0.00	) EUR		Repair pair 211.80 EUF		New paint - E		<b>Depr.</b> 50 %		Total 211.80 EUR	
x]		) EUR REEN/LEFT				New paint - E	GE			1	
x]		REEN/LEFT		211.80 EUF	2			50 %		1	
[x]	WINDSCF Number	REEN/LEFT Code		211.80 EUF	1		Unit pri	50 % ce Depr.		211.80 EUR Total	
[x]	WINDSCF Number	REEN/LEFT		211.80 EUF	1			50 % ce Depr.		211.80 EUR	
x]	WINDSCF Number	REEN/LEFT Code	3	211.80 EUF	1		Unit pri	50 % ce Depr.	9	211.80 EUR Total	
[x]	WINDSCF Number 2 I 1	REEN/LEFT Code i-vab-herstr-01	<b>3</b> 211.80	211.80 EUF Description WINDOW	REPAIR	WINDOW DAMAG	Unit pri 58.80 EU	50 % ce Depr. JR	<b>9</b> 0	211.80 EUR Total 58.80 EUR	
x]	WINDSCF Number 2 I 1	REEN/LEFT Code i-vab-herstr-01 2		211.80 EUF Description WINDOW	R REPAIR 5	WINDOW DAMAG	Unit pri 58.80 EU 7	50 % ce Depr. JR 8		211.80 EUR Total 58.80 EUR 10	
x]	WINDSCF Number 2 I 1 0	REEN/LEFT Code i-vab-herstr-01 2 58.80 58.80	211.80 105.90	211.80 EUF Description WINDOW 4 0	REPAIR 5 0	WINDOW DAMAG	Unit pri 58.80 EU 7 0	50 % ce Depr. JR 8 0	0	211.80 EUR Total 58.80 EUR 10 0	
x]	WINDSCF 2 Number 2 I 1 0 0	REEN/LEFT Code i-vab-herstr-01 2 58.80 58.80 ATIVE	211.80 105.90 TRADI	211.80 EUR Description WINDOW 4 0 0	REPAIR 5 0	WINDOW DAMAG	Unit pri 58.80 EU 7 0	50 % ce Depr. JR 8 0	0	211.80 EUR Total 58.80 EUR 0 0 0	
	WINDSCF Number 2 I 1 0 0 INNOV	REEN/LEFT Code i-vab-herstr-01 2 58.80 58.80 ATIVE 80	211.80 105.90 TRADI 211	211.80 EUF Description WINDOW 4 0 0 TIONAL	REPAIR 5 0	WINDOW DAMAG	Unit pri 58.80 EU 7 0	50 % ce Depr. JR	0	211.80 EUR Total 58.80 EUR 10 0	

164.70

# fleet services

# **APPRAISAL**

www.vabfleetservices.be

26/07/2017 Date :

[x] = Status Modification

#### Pictures : No CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time :	0 min	Waiting time :	0 min	Towing time :	0 min
		Reason :		Reason :	
NOT EXECUTED :	No				
Reason :					
Remark :					

Prices in EUR without VAT

Authorized by customer :				Executed by VAB Fleet Services
Remark authorized cust	omer :			
Date :	26/07/2017	Hour :	14:14	
Company :				
Executed by VAB Fleet Services				
E-Mail :	@			
Signature authorized by c	ustomer			
-				