

www.vabfleetservices.be

## **APPRAISAL**

Date : 20/07/2017 1/5

BSRBQK

#### [] NOT EXECUTED **[X] EFFECTIVE**

[X] COLLECTION

[] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	52101 KM
File nr. :	1415260	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EPZ554 / YV1MV8481D204	0417 /	yr of constructionr :	/
E-File nr. :		First registration :	19/02/2013
VFS-nr. :		Color :	BLACK
Make + Model :	VOLVO / V40	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	94g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	V40 D2 Base 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
нр:	114	kW:	84
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		1	

## fleet services

## **APPRAISAL**

www.vabfleetservices.be

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	ОК	[X]	Oil level :		
Jack, wheelspanner :			Filled up :	0	

### Wheels and tyres: Summer tires

				_									
Wheel FL:	[x]	MIC	CHELIN	Tyre :		OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :	
Wheel RL :	[x]	MIC	CHELIN	Tyre :		OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :	
Wheel FR :	[x]	MIC	CHELIN	Tyre :	[x]	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :	
Wheel RR :	[x]	MIG	CHELIN	Tyre :		OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :	
Wheel RES:	[x]	AN	DERE	Tyre :		OK		/	Rim :			/ Hubcap :	
			<b></b>		-				i				
		[x]		Width			He	eight			Туре	Rim	Index
Fro	nt tyre			<b>Width</b> 205				e <b>ight</b> 55			<b>Type</b> R	<b>Rim</b> 16	Index H
	nt tyre ar tyre				+			8					

### Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/ Hubcap:
Wheel RL :	Tyre :	OK	/	Rim :	/ Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/ Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/ Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/ Hubcap :

Front tyre 0 0 R 0   Rear tyre 0 0 R 0		[ <b>x</b> ]	Width	Height	Туре	Rim	Index
<b>Rear tyre</b> 0 0 R 0	Front ty	re	0	0	R	0	
	Rear ty	re	0	0	R	0	

Remark :

2/5

# A CARACTERISTICS

## APPRAISAL

www.vabfleetservices.be

Date : 20/07/2017

#### Conclusion

#### Bodywork \& windows

[x] REAR BUMPER/LEFT/LEFT

OTHER DAMAGES

HERST OVBH

3/5

### STATUS: ACCEPTABLE / USAGE DAMAGE

Bod	Bodywork \& windows							
[x]	REAR MUDGUARD/RIGHT/REAR	DENT						
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)						
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT						
[x]	ROOF/CENTER/RIGHT	DENT						
[x]	ROOF STYLE/CENTER/RIGHT	DENT						
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	RAND					
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE						
[x]	FRONT DOOR/RIGHT/CENTER	DENT						
[x]	FRONT MUDGUARD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE						
[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE	ONDER					
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS						
[x]	FRONT BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	ONDER					
[x]	FRONT BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE	ONDER					

## STATUS: NOT ACCEPTABLE

#### Bodywork \& windows REAR DOOR/CENTER/LEFT [x] SCRATCH WITH PAINT DAMAGE Repair paint - LI New paint - E Total Depr. **3** 0 LU =0.00 EUR 301.68 EUR 301.68 EUR 50%[x] REAR MUDGUARD/LEFT/FRONT DENT Repair paint - LI New paint - E Total Depr. 2 0 LU =0.00 EUR 308.20 EUR 308.20 EUR 50 %



## APPRAISAL

www.vabflee	vw.vabfleetservices.be					Date : 20/07/2017			
[x] REAR DO	OOR/LEFT/REAR				SCRATCH WITH				
			Repair pain	nt - LI	New paint - E		Depr.		Total
<b>2</b> 0 LU =0.0	00 EUR		318.35 EUR				50 %		318.35 EUR
[x] REAR DO	OOR/RIGHT/FRO	NT			SCRATCH WITH	PAINT DAMAG	Е		
			Repair pair	nt - LI	New paint - E		Depr.		Total
4 0 LU =0.0	00 EUR		318.35 EUR				50 %		318.35 EUR
[x] FRONT	THRESHOLD/RIG	HT/REAR			SCRATCH WITH	PAINT DAMAG	E		
			Repair pair	nt - LI	New paint - E Depr.				Total
<b>5</b> 0 LU =0.0	00 EUR		310.50 EUR				50 %		310.50 EUR
RIM FRO Number	ONT LEFT Code		Description			Unit pr	ice Depr.		Total
<b>1</b> I 1	i-vab-herstalu-02	2	REPAIR AL	LOY WHEEI	_	95.00 E	UR		95.00 EUR
1	2	3	4	5	6	7	8	9	10
95.00	626.55	301.68	318.35	310.50	0	0	0	0	0
95.00	313.28	150.84	159.18	155.25	0	0	0	0	0
INNO	INNOVATIVE TRADIT		TIONAL		GENERAL				
95	5.00	155	57.08		0	0			1652.08
НС	0G: 0	В	G: 0			NA Dep	NA Deprec. 8		
				-		0.00%	6		

TOTAL 873.54

# VAB fleet services

## APPRAISAL

www.vabfleetservices.be

Date : 20/07/2017

[x] = Status Modification

#### Pictures : No CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time :	0 min	Waiting time :	0 min	Towing time :	0 min
		Reason :		Reason :	
NOT EXECUTED :	No				
Reason :					
Remark :					

Prices in EUR without VAT

Authorized by customer :				Executed by VAB Fleet Services
	F THE VEHICLE AND I A ITS;	GREE WITH THE	REPORT	
Remark authorized cust	comer :			
Date :	20/07/2017	Hour :	10:23	
Company :				
Executed by VAB Fleet Services				
E-Mail :	@			
Signature authorized by c	ustomer			
-			$\checkmark$	