

www.vabfleetservices.be Date: 11/08/2017 1/4

CADJ6C

[X] EFFECTIVE [] NOT EXECUTED	[] COLLECTION	[] DELIVERY
-----------------	----------------	----------------	--------------

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner:		Mileage :	143142 KM
File nr. :	1428903	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1LDP157 / YF1FW84A	ID1135306 /	yr of constructionr:	/
E-File nr. :		First registration :	25/06/2013
VFS-nr. :		Color :	BLACK
Make + Model :	VOLVO / V60	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel:	
Classification :		Environment Class:	EURO 5
Customer company :	ONBEKEND	Co2:	119g/km
Driver :		Remote controls:	2
Covering:	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan):	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			



Date: 11/08/2017 www.vabfleetservices.be 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Winter tires

Wheel FL:	[x]	MICI	HELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	,	Hubcap:	
Wheel RL:	[x]	MICI	HELIN	Tyre:		OK	[x]	2-4 /	Rim:			,	Hubcap:	
Wheel FR:	[x]	MICI	HELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	,	Hubcap:	
Wheel RR:	[x]	MICI	HELIN	Tyre:		OK	[x]	2-4 /	Rim:			,	Hubcap:	
Wheel RES:	[x]			Tyre:		OK		/	Rim:			,	Hubcap:	
		_												
		[x]	W	idth			He	ight			Type		Rim	Index
Front tyre			2	205			(50			R		16	M+S

	[X]	Width	Height	Туре	Rim	Index
Fro	ont tyre	205	60	R	16	M+S
Res	ear tyre	205	60	R	16	M+S

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 11/08/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Во	dywork \& windows	
[x]	REAR BUMPER/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

BONNET/CENTER/LEFT/FRONT

[x] BONNET/CENTER/RIGHT DENT

_	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

SCRATCH (WITHOUT PAINT DAMAGE)

Others

[x]

RIM FRONT LEFT

	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number		Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

	1	2	3	4	5	6	7	8	9	10
	63.00	190.00	0	0	0	0	0	0	0	0
ſ	63.00	190.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
253.00	0	0		253.00
HOG: 0	BG: 0		NA Deprec.	253.00
		0.00%		

TOTAL

253.00



www.vabfleetservices.be Date: 11/08/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time :	0 min	Waiting time: 0 mi	in	Towing time :	0 min
		Reason:		Reason:	
NOT EXECUTED	: No				
Reason:					
Remark:					
Prices in EUR	without VAT				
Authorized by			Executed by VAB Fleet S	ervices	1
customer :			2.1000.5		
Remark authorized	l customer :				
Date :	11/08/2017	Hour: 11:07			
Company :					
Executed by VAB l Services	Fleet				
E-Mail :	@				
Signature authorized	l by customer				
_		/			
	_				