

www.vabfleetservices.be Date: 07/09/2017 1/4

CIX2GQ

[X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	117102 KM
File nr. :	1435529	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ERM199 / WBA3E11080J70	8880 /	yr of constructionr :	/
E-File nr. :		First registration :	01/03/2013
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / 3	Fuel type :	DIESEL
Object nr. :		Fuel:	
Classification:		Environment Class:	EURO 5
Customer company :	XPERTHIS NV	Co2:	109g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	3 BER 320d Eff.Dynamics Ed.163PK	Country registration :	BELGIUM

		•		
Variant car:	BERLINE	Engine size:	1995	
Gear box :	Manueel	Number of places:	5	
Number of gears:	6	Number of doors:	4	
НР:	163	kW:	120	
Fisc HP		Imported vehicle:		
Animals transported:	No	Smoked in vehicle:	No	
Due date vehicle inspection:		Extra set of tires:		
		Use:	Unknown	
General condition:				

Metallic paint:

Yes



Date: 07/09/2017 www.vabfleetservices.be 2/4

Original registr. number : OK Service manual:

Cert. of reg. / Part 1:

Cert. of conformity: OK Insurance certificate: Cert. of reg. copy / Part 2: OK [x]

Warning vest: Transport licence: Tax certificate: Navigation CD/SD/DVD

Fuel card : Car radio: OK [x]

Mobile phone kit : Extinguisher: OK [x]

> Warning triangle: OK [x]

> > 0

Oil level: OK OK First aid kit : [x] [x]

Filled up: Jack, wheelspanner :

## Wheels and tyres: Summer tires

Wheel FL:	MICHELIN	Tyre:	OK	4-6 /	Rim:	/ Hubcap:
Wheel RL:	MICHELIN	Tyre:	OK	4-6 /	Rim:	/ Hubcap:
Wheel FR:	MICHELIN	Tyre:	OK	4-6 /	Rim:	/ Hubcap:
Wheel RR:	MICHELIN	Tyre:	OK	4-6 /	Rim:	/ Hubcap:
Wheel DES:		Tyre ·	OK	/	Rim ·	/ Hubean

	Width	Height	Туре	Rim	Index
Front tyre	205	60	R	16	W
Rear tyre	205	60	R	16	W

Remark:

### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 07/09/2017 3/4

### STATUS: ACCEPTABLE / USAGE DAMAGE

FRONT BUMPER/CENTER/RIGHT

[x]

#### Bodywork \& windows [x] REAR MUDGUARD/RIGHT/CENTER DENT FRONT DOOR/LEFT/CENTER DENT [x] ROOF STYLE/FRONT/LEFT/CENTER CHIPS [x] WINDSCREEN/CENTER/RIGHT **CHIPS** [x] FRONT DOOR/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE) [x] FRONT MUDGUARD/LEFT/FRONT **CHIPS** BONNET/CENTER/RIGHT/FRONT **CHIPS** [x]

	1	2	3	4	5	6	7	8	9	10
	0	0	0	0	0	0	0	0	0	0
ſ	0	0	0	0	0	0	0	0	0	0

**CHIPS** 

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 0		NA Deprec. 0
			0.00%

TOTAL

0



07/09/2017 Date: www.vabfleetservices.be 4/4

[x] = Status Modification

**Pictures:** No

CIRCUMSTANCES

CIRCUMSTANCES			NORMAL CONCLUSION				
Extra Time :	0 min	Waiting time: 0 mi Reason:	n	Towing time : Reason :	0 min		
NOT EXECUTED : Reason :	No	I					
Remark:	[x]						
Prices in EUR v	vithout VAT						
Authorized by customer :			Executed by VAB Fleet	Services			
customer: I KNOW THE STATE OF THE VEHICLE AND I AGREE WITH THE REPORT AND ITS ATTACHMENTS;							
Remark authorized	customer :						
Date :	07/09/2017	<b>Hour:</b> 12:18					
Company:							
Executed by VAB F. Services	leet						
E-Mail :	@						
Signature authorized	by customer						