

APPRAISAL

www.vabfleetservices.be Date: 13/09/2017 1/4

CJMTBQ

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar: **KBC REMARKETING** Cleanliness: INT: DIRTY [x] EXT: CLEAN [x] Owner: Mileage : 137450 KM File nr. : Mileage start / arrival: 1436074 0 / 0Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1DKJ064 / WBA1C91010J197816 / E-File nr. : First registration: 08/06/2012 VFS-nr.: Color: **BLACK**

Make + Model : BMW / 1 Fuel type : DIESEL

Object nr.: Fuel:

Classification: Environment Class: EURO 5

Customer company: KBC BANK NV Co2: 99g/km

Driver: Remote controls: 2

Covering: TISSUE Number keys: 2[x] Vehicle kind: VEHICLE Seats (minivan): 0

 Vehicle type :
 1 HATCH 116d Eff.Dyn.Ed. 116PK
 Country registration :
 BELGIUM

Metallic paint: VAT over the margin - car: No 1598 Variant car: Engine size: Gear box : Number of places: Manueel 5 Number of gears: 6 Number of doors: 5 HP: kW: 116 85 Fisc HP Imported vehicle: No Smoked in vehicle: Animals transported: No No Due date vehicle inspection: Extra set of tires: No Use: Unknown

General condition:



Jack, wheelspanner :

APPRAISAL

www.vabfleetservices.be Date: 13/09/2017 2/4

Original registr. number : OK Service manual : Cert. of conformity: Cert. of reg. / Part 1: OK OK [x] Cert. of reg. copy / Part 2: Insurance certificate: Transport licence: Warning vest: OK [x] Tax certificate: Navigation CD/SD/DVD Fuel card : Car radio: OK [x] Extinguisher: Mobile phone kit : OK [x] Warning triangle: OK [x] Oil level: First aid kit : OK OK [x] [x]

Filled up:

0

Wheels and tyres: Summer tires

Front tyre Rear tyre		\dashv	205 205		+	55 55					R R		16	W
		[x]			+	Height				Туре		Rim	Index	
		1		XX7* 141			***	.1.1.4			TD.		D'	T. 1
Wheel RES:	[x]			Tyre:		OK		/	Rim:				/ Hubcap:	
Wheel RR:	[x]	UNIF	ROYAL	Tyre:		OK	[x]	2-4 /	Rim:				/ Hubcap:	
Wheel FR:	[x]	MICI	HELIN	Tyre:	[x]	OK	[x]	1.6-2 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel RL:	[x]	UNIF	ROYAL	Tyre:		OK	[x]	2-4 /	Rim:				/ Hubcap:	
Wheel FL:	[x]	MICI	HELIN	Tyre:		OK	[x]	1.6-2 /	Rim:				/ Hubcap:	

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

 [x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



APPRAISAL

www.vabfleetservices.be Date: 13/09/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/RIGHT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)

[x] FRONT DOOR/RIGHT/REAR DENT

STATUS: NOT ACCEPTABLE

Others

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	I 4	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		58.32 EUR

1	2	3	4	5	6	7	8	9	10
58.32	0	0	0	0	0	0	0	0	0
58.32	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
58.32	0	0		58.32
HOG: 0	BG: 0		NA Deprec.	58.32
			0.00%	

0.00%
TOTAL 58.32



APPRAISAL

www.vabfleetservices.be Date: 13/09/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS	TANCES		NORMAL CONCLUSION					
Extra Time :	0 min	Waiting time: 0 min Reason:	n	Towing time: 0 min Reason:				
NOT EXECUTED : Reason :	No	I		<u> </u>				
Remark:								
Prices in EUR v	vithout VAT							
Authorized by customer :			Executed by VAB Fleet S	ervices				
Remark authorized	customer :							
Date :	13/09/2017	Hour: 13:09						
Company:								
Executed by VAB F Services	leet							
E-Mail :	@							
Signature authorized	by customer							
_								