

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|-----------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 118827 KM |
| File nr. : | 1437579 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1GDR190 / WBA5J31050D710438 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 09/01/2014 |
| VFS-nr. : | | Color : | GREY |
| Make + Model : | BMW / 5 TOURING | Fuel type : | DIESEL |
| Object nr. : | 35275 | Fuel : | |
| Classification : | | Environment Class: | EURO 6 |
| Customer company : | EDF LUMINUS | Co2: | 129g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|-------------------|----------------------------|---------|
| VAT over the margin - car: | | Metallic paint: | Yes |
| Variant car: | BREAK | Engine size: | 1995 |
| Gear box : | Automaat algemeen | Number of places: | 5 |
| Number of gears: | | Number of doors: | 5 |
| HP: | 163 | kW: | 120 |
| Fisc HP | | Imported vehicle: | No |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

General condition:

| | | | | |
|------------------------------|----|-------------------------|-----------------------|-----|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | OK | [x] | Cert. of conformity : | OK |
| Cert. of reg. copy / Part 2: | | Insurance certificate : | | [x] |
| Warning vest : | OK | [x] | Transport licence : | |
| Tax certificate : | | Navigation CD/SD/DVD | OK | [x] |
| Fuel card : | | Car radio : | OK | [x] |
| Mobile phone kit : | | Extinguisher : | OK | [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK |
| Jack, wheelspanner : | | Oil level : | OK | [x] |
| | | Filled up : | 0 | |

Wheels and tyres: Summer tires

| | | | | | | | | | | | | |
|------------|-----|----------|--------|-----|-----|------|-------|-------|-----------------|-----------------|----------|----------|
| Wheel FL: | [x] | MICHELIN | Tyre : | OK | [x] | 4-6/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : | |
| Wheel RL : | [x] | MICHELIN | Tyre : | OK | [x] | 2-4/ | Rim : | | | / | Hubcap : | |
| Wheel FR : | [x] | MICHELIN | Tyre : | [x] | OK | [x] | 4-6/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : |
| Wheel RR : | [x] | MICHELIN | Tyre : | OK | [x] | 2-4/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : | |
| Wheel RES: | [x] | | Tyre : | OK | | / | Rim : | | | / | Hubcap : | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225 | 55 | R | 17 | Y |
| Rear tyre | 225 | 55 | R | 17 | Y |

Remark :

Wheels and tyres:

| | | | | | | | | |
|------------|--|--------|----|---|-------|--|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] WINDSCREEN/CENTER/RIGHT CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| [x] | REAR DOOR/RIGHT/RIGHT | SCRATCH WITH PAINT DAMAGE | +DEUK | | |
|-----|---------------------------|---------------------------|---------------|-------|------------|
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 3 | 0 LU =0.00 EUR | 362.02 EUR | | 50 % | 362.02 EUR |
| [x] | FRONT BUMPER/RIGHT/CORNER | SCRATCH WITH PAINT DAMAGE | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 2 | 0 LU =0.00 EUR | 254.16 EUR | | | 254.16 EUR |

Others

RIM REAR RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 1 | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR |

RIM FRONT RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 1 | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|--------|--------|---|---|---|---|---|---|----|
| 190.00 | 254.16 | 362.02 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 190.00 | 254.16 | 181.01 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 190.00 | 616.18 | 0 | 806.18 |
| HOG: 0 | BG: 2 | | NA Deprec. 625.17 |
| | | | 0.00% |
| | | | TOTAL 625.17 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 12/09/2017 Hour : 14:38 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |