

www.vabfleetservices.be Date: 11/09/2017 1/4

CIBS6X

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	169679 KM
File nr. :	1435101	Mileage start / arrival:	0/0
Reg number / Chassis / Ref :		Mileag ref. service :	0
IERM219 / WBA1N31070J71	0669 /	yr of constructionr :	/
E-File nr. :		First registration :	01/03/2013
VFS-nr. :		Color :	BROWN
Make + Model :	BMW / 1	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification:		Environment Class:	EURO 5
Customer company :	KBC BANK NV	Co2:	99g/km
Driver :		Remote controls:	2
Covering:	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan):	0
Vehicle type :	1 SPORTSHATCH 116d Eff.Dyn.Ed.116PK	Country registration :	BELGIUM

Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
нр:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Metallic paint:

Yes



www.vabfleetservices.be Date: 11/09/2017 2/4

Original registr. number : OK Service manual : Cert. of conformity: Cert. of reg. / Part 1: OK Insurance certificate: Cert. of reg. copy / Part 2: OK [x]Warning vest: Transport licence: Tax certificate: Navigation CD/SD/DVD Fuel card : OK [x] Car radio: OK [x] Extinguisher: Mobile phone kit : OK [x] Warning triangle: OK [x] Oil level: OK OK First aid kit : [x] [x]

Filled up:

0

Wheels and tyres: Summer tires

		[x]	Width			eight			Туре	Rim	Index
Wheel RES:	[x]		Tyre:	OK		/	Rim:			/ Hubcap:	
Wheel RR:	[x]	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	Hubcap:	
Wheel FR:	[x]	MICHELIN	Tyre: [x] OK	[x]	2-4 /	Rim:			/ Hubcap:	
Wheel RL:	[x]	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim:			/ Hubcap:	
Wheel FL:	[x]	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	Hubcap:	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	W
Rear tyre	205	55	R	16	W

Remark: REPSET OK

Jack, wheelspanner :

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 11/09/2017 3/4

STATUS: NOT ACCEPTABLE

RIM FRO	ONT LEFT								
Number	Code		Description	l		Unit price	Depr.		Total
1 I I	i-vab-herstalu-02		REPAIR AI	LLOY WHEEL		95.00 EUR	-		95.00 EU
RIM RE	AR RIGHT								
Number	Code		Description	ı		Unit price	Depr.		Total
1 I.1 i-vab-herstalu-02						95.00 EUR			
1 I 1	i-vab-herstalu-02		REPAIR AI	LLOY WHEEL		95.00 EUR			95.00 EU
1 11	i-vab-herstalu-02	3	REPAIR AI	LLOY WHEEL	6	95.00 EUR	8	9	95.00 EU
		3			6			9	_
1	2		4	5		7	8		
1 190.00 190.00	2	0	4 0	5 0 0	0	7	8	0	10 0
1 190.00 190.00 INNO	2 0 0	0	4 0 0	5 0 0	0	7	8	0	0 0
1 190.00 190.00 INNO	2 0 0	0 0 TRAD	4 0 0	5 0 0	0 0 ENERAL	7	8 0 0	0	10

TOTAL

190.00



11/09/2017 Date: www.vabfleetservices.be 4/4

[x] = Status Modification

Pictures: No

CIRCUMS	TANCES		UNDER C	ONDITION - VEHICLE WET		
Extra Time :	0 min	Waiting time: 0 Reason:	min	Towing time : Reason :	0 min	
NOT EXECUTED : Reason :	: No	'		•		
Remark:						
Prices in EUR v	without VAT					
Authorized by customer:			Executed by VA	B Fleet Services		
Remark authorized	customer :					
Date :	11/09/2017	Hour: 15:54				
Company:						
Executed by VAB F Services	leet					
E-Mail :	@					
Signature authorized	by customer					