

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|---------------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 198449 KM |
| File nr. : | 1436223 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1EBJ086 / WAUZZZ4G4DN063648 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 10/10/2012 |
| VFS-nr. : | | Color : | BLACK |
| Make + Model : | AUDI / A7 | Fuel type : | DIESEL |
| Object nr. : | 52632 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | TIENSE SUIKERRAFFINADERIJ NV | Co2: | 152g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | A7 SB Quattro S-tr.204PK Aut. | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|-------------------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | | Engine size: | 2967 |
| Gear box : | Automaat algemeen | Number of places: | 5 |
| Number of gears: | | Number of doors: | 5 |
| HP: | 204 | kW: | 150 |
| Fisc HP | | Imported vehicle: | No |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

General condition:

| | | | | |
|------------------------------|----|-----------------------|-------------------------|--------|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | | Cert. of conformity : | OK | |
| Cert. of reg. copy / Part 2: | OK | [x] | Insurance certificate : | |
| Warning vest : | OK | [x] | Transport licence : | |
| Tax certificate : | | | Navigation CD/SD/DVD | OK [x] |
| Fuel card : | | | Car radio : | OK [x] |
| Mobile phone kit : | | | Extinguisher : | OK [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK [x] |
| Jack, wheelspanner : | | | Oil level : | OK [x] |
| | | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | | |
|------------|-----|----------|--------|-----|-----|------|-------|-------|-----------------|----------------------------|
| Wheel FL: | [x] | PIRELLI | Tyre : | OK | [x] | 2-4/ | Rim : | [x] | / | Hubcap : |
| Wheel RL : | [x] | UNIROYAL | Tyre : | OK | [x] | 2-4/ | Rim : | [x] | WHEEL SCRATCHED | / Hubcap : |
| Wheel FR : | [x] | PIRELLI | Tyre : | [x] | OK | [x] | 2-4/ | Rim : | [x] | WHEEL SCRATCHED / Hubcap : |
| Wheel RR : | [x] | UNIROYAL | Tyre : | OK | [x] | 2-4/ | Rim : | | / | Hubcap : |
| Wheel RES: | [x] | | Tyre : | OK | | / | Rim : | | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 235 | 55 | R | 17 | Y |
| Rear tyre | 235 | 55 | R | 17 | Y |

Remark :

Wheels and tyres:

| | | | | | | | | |
|------------|--|--------|----|---|-------|--|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | |
|-----|------------------------|---|
| [x] | REAR DOOR/CENTER/RIGHT | SCRATCH WITH PAINT DAMAGE |
| [x] | REAR DOOR/RIGHT/CENTER | DENT |
| [x] | FRONT DOOR/LEFT/CENTER | DENT |
| [x] | BONNET/CENTER/LEFT | SCRATCH (WITHOUT PAINT DAMAGE) POLIEREN |

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | | |
|-----|---------------------------|---------------------------|----------------------|--------------|--------------|
| [x] | REAR BUMPER/CENTER/LEFT | SCRATCH WITH PAINT DAMAGE | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 3 | 0 LU =0.00 EUR | 254.16 EUR | | 50 % | 254.16 EUR |
| [x] | REAR MUDGUARD/RIGHT/FRONT | SCRATCH WITH PAINT DAMAGE | | +DEUK | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 4 | 0 LU =0.00 EUR | 369.84 EUR | | 50 % | 369.84 EUR |
| [x] | FRONT BUMPER/RIGHT | SCRATCH WITH PAINT DAMAGE | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 2 | 0 LU =0.00 EUR | 254.16 EUR | | 50 % | 254.16 EUR |

Others

RIM REAR LEFT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 2 | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR |

RIM FRONT RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 1 | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|--------|--------|--------|---|---|---|---|---|----|
| 95.00 | 349.16 | 254.16 | 369.84 | 0 | 0 | 0 | 0 | 0 | 0 |
| 95.00 | 222.08 | 127.08 | 184.92 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 190.00 | 878.16 | 0 | 1068.16 |
| HOG: 0 | BG: 2 | | NA Deprec. 629.08 |
| | | | 0.00% |
| | | | TOTAL 629.08 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---------------------------|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No | | |
| Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 11/09/2017 Hour : 11:20 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |