

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	160340 KM
File nr. :	1435993	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HTP597 / WBA3K11070F834224 /		yr of constructionr :	/
E-File nr. :		First registration :	30/09/2014
VFS-nr. :		Color :	WHITE
Make + Model :	BMW / 3 TOURING	Fuel type :	DIESEL
Object nr. :	38523	Fuel :	
Classification :	F	Environment Class:	EURO 5
Customer company :	KUPPERSBUSCH BVBA	Co2:	119g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RL :	Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel FR :	Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RR :	Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RES:	Tyre :	OK	/	Rim :		/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	0	0		0	
Rear tyre	0	0		0	

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RL :	Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel FR :	Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RR :	Tyre :	OK	/	Rim :		/	Hubcap :	
Wheel RES:	Tyre :	OK	/	Rim :		/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	0	0		0	
Rear tyre	0	0		0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] BONNET/CENTER/LEFT/FRONT CHIPS
- [x] FRONT BUMPER/CENTER/RIGHT CHIPS

Interior

- [x] CENTER CONSOLE OTHER DAMAGES

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	DENT			
			Repair paint - LI	New paint - E	Depr.
2	15 LU =72.00 EUR		0 EUR	235.80 EUR	50 %
					Total
					307.80 EUR

[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE			
			Unit price	Depr.	Total
1	I 1 i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR
			Unit price	Depr.	Total
1	I 1 i-vab-herstr-02	SUPPL WINDOW REPAIR	29.40 EUR		29.40 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	REAR BUMPER	343.20 EUR	50 %	343.20 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	REFLEKTOR	10.00 EUR	50 %	10.00 EUR

1	2	3	4	5	6	7	8	9	10
88.20	661.00	0	0	0	0	0	0	0	0
88.20	330.50	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
88.20	661.00	0	749.20
HOG: 0	BG: 0		NA Deprec. 418.70
			0.00%
			TOTAL 418.70

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/09/2017 Hour : 10:04 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	