

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	95796 KM
File nr. :	1430296	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CRA652 / ZFA25000002136203 /		yr of constructionr :	/
E-File nr. :		First registration :	07/02/2012
VFS-nr. :		Color :	GREY
Make + Model :	FIAT / DUCATO	Fuel type :	DIESEL
Object nr. :	34215	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Deceuninck nv	Co2:	195g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	DUCATO 33 B/F LWB HR 130PK (EU5)	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BESTELWAGEN	Engine size:	2287
Gear box :	Manueel	Number of places:	3
Number of gears:	6	Number of doors:	5
HP:	131	kW:	96
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	70	R	15	H
Rear tyre	215	70	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE		
[x]	REAR DOOR/RIGHT/CENTER	OTHER DAMAGES	WELVING	
[x]	THRESHOLD FRONT/LEFT/CENTER	OTHER DAMAGES	DEURRUBBER	

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	SCRATCH WITH PAINT DAMAGE		
-----	------------------------------	---------------------------	--	--

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	DENT				
		Repair paint - LI	New paint - E	Depr.	Total	
1	10 LU =48.00 EUR	231.15 EUR		50 %	279.15 EUR	
[x]	REAR THRESHOLD/RIGHT/FRONT	DENT				
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	ROOF STYLE/FRONT/LEFT/CENTER	DENT				
		Repair paint - LI	New paint - E	Depr.	Total	
3	20 LU =96.00 EUR	165.14 EUR		50 %	261.14 EUR	
[x]	FRONT DOOR/RIGHT/REAR	DENT		+LAKSCHADE		
		Repair paint - LI	New paint - E	Depr.	Total	
2	0 LU =0.00 EUR	238.76 EUR		50 %	238.76 EUR	

1	2	3	4	5	6	7	8	9	10
279.15	238.76	261.14	63.00	0	0	0	0	0	0
139.58	119.38	130.57	63.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	779.05	0	842.05
HOG: 0	BG: 3		NA Deprec. 452.52
			0.00%
			TOTAL 452.52

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 30/08/2017 Hour : 08:57 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	