

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	86350 KM
File nr. :	1435149	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HES450 / JTHBH1BL105002520 /		yr of constructionr :	/
E-File nr. :		First registration :	02/07/2014
VFS-nr. :		Color :	GREY
Make + Model :	LEXUS / GS	Fuel type :	HYBRID
Object nr. :	734	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	TERUMO BCT EUROPE NV	Co2:	113g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	2494
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	4
HP:	181	kW:	133
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1: OK [x]	Cert. of conformity : OK
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest : OK [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD OK [x]
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner : OK [x]	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] DUNLOP	Tyre : OK [x] 2-4/	Rim : [x] WHEEL SCRATCHED	Hubcap :
Wheel RL : [x] DUNLOP	Tyre : OK [x] 2-4/	Rim : [x] WHEEL SCRATCHED	Hubcap :
Wheel FR : [x] DUNLOP	Tyre : [x] OK [x] 2-4/	Rim : [x] WHEEL SCRATCHED	Hubcap :
Wheel RR : [x] DUNLOP	Tyre : OK [x] 2-4/	Rim : [x] WHEEL SCRATCHED	Hubcap :
Wheel RES: [x]	Tyre : OK /	Rim :	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	235	45	R	18	Y
Rear tyre	235	45	R	18	Y

Remark :

Wheels and tyres:

Wheel FL:	Tyre : OK /	Rim :	Hubcap :
Wheel RL :	Tyre : OK /	Rim :	Hubcap :
Wheel FR :	Tyre : OK /	Rim :	Hubcap :
Wheel RR :	Tyre : OK /	Rim :	Hubcap :
Wheel RES:	Tyre : OK /	Rim :	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR
[x]	REAR DOOR/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE	MEERDERE	
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	382.02 EUR		50 %	382.02 EUR
[x]	BONNET/CENTER/LEFT		OTHER DAMAGES	CHEMISCHE INWERKING	
		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR	348.09 EUR		50 %	348.09 EUR
[x]	FRONT MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE	ROEST	
	Number Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR
[x]	FRONT BUMPER/RIGHT		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
6	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
6	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
6	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
6	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
254.16	115.56	382.02	254.16	348.09	380.00	0	0	0	0
127.08	115.56	191.01	127.08	174.04	380.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
495.56	1238.43	0	1733.99
HOG: 0	BG: 2		NA Deprec. 1114.78
			0.00%
			TOTAL 1114.78

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 08/09/2017 Hour : 16:48 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	