

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	174294 KM
File nr. :	1436755	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EVN497 / WF0LXXGCBLDU81483 /		yr of constructionr :	/
E-File nr. :		First registration :	01/04/2013
VFS-nr. :		Color :	BLACK
Make + Model :	FORD / FOCUS CLIPPER	Fuel type :	DIESEL
Object nr. :	58469	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	PIETERCIL DELBY'S NV	Co2:	88g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	FOCUS CLIP. EConetic Trend 88g 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	OK [x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :		
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	[x]	MISSING/INCOMPLETE
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] ROOF STYLE/CENTER/RIGHT SCRATCH (WITHOUT PAINT DAMAGE) POLIEREN
- [x] BONNET/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE) POLIEREN

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT		DENT					
	Number	Code	Description	Unit price	Depr.	Total		
5	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR		
[x]	REAR DOOR/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE					
	Number	Code	Description	Unit price	Depr.	Total		
0	0							
[x]	REAR DOOR/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE					
	Number	Code	Description	Unit price	Depr.	Total		
0	0							
[x]	REAR DOOR/RIGHT/RIGHT		SCRATCH WITH PAINT DAMAGE					
	Number	Code	Description	Unit price	Depr.	Total		
0	0							
[x]	REAR MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE					
			Repair paint - LI	New paint - E	Depr.	Total		
6	0 LU =0.00 EUR		308.20 EUR		50 %	308.20 EUR		
[x]	REAR DOOR/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE		+DEUK			
			Repair paint - LI	New paint - E	Depr.	Total		
4	0 LU =0.00 EUR		318.35 EUR		50 %	318.35 EUR		
[x]	REAR THRESHOLD/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE					
			Repair paint - LI	New paint - E	Depr.	Total		
8	0 LU =0.00 EUR		310.50 EUR		50 %	310.50 EUR		
[x]	REAR DOOR/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE		+DEUK			
			Repair paint - LI	New paint - E	Depr.	Total		
7	0 LU =0.00 EUR		318.35 EUR		50 %	318.35 EUR		

[x]	FRONT MUDGUARD/LEFT/FRONT		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR
[x]	FRONT BUMPER/LEFT/SIDE		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	FRONT BUMPER/RIGHT		SCRATCH WITH PAINT DAMAGE		
	Number Code	Description	Unit price	Depr.	Total
0	0				
[x]	REAR DOOR/LEFT/LEFT		SCRATCH WITH PAINT DAMAGE	+DEUK	
		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR	301.68 EUR		50 %	301.68 EUR

Interior

[x]	CARPET FL		HOLE		
	Number Code	Description	Unit price	Depr.	Total
9	I 1 i-vab-inttap-01	CARPET REPAIR (MAX 3CM LENGTH OR DIAMETER)	43.92 EUR		43.92 EUR
	Number Code	Description	Unit price	Depr.	Total
9	I 1 i-vab-inttap-02	SUPPL REPAIR CARPET	18.00 EUR		18.00 EUR

Others

CLEANLINESS INTERIOR

	Number Code	Description	Unit price	Depr.	Total
1	I 5 speciefiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		72.90 EUR

HUB CAP REAR RIGHT

		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR			50 %	

Pieces

	Number Code	Description	Unit price	Depr.	Total
2	1 WHEEL CAP		30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
72.90	30.00	431.98	318.35	412.32	308.20	318.35	310.50	61.92	0
72.90	15.00	215.99	159.18	261.48	154.10	159.18	155.25	61.92	0

INNOVATIVE	TRADITIONAL	GENERAL	
245.46	2019.06	0	2264.52
HOG: 0	BG: 0		NA Deprec. 1254.99
			0.00%
			TOTAL 1254.99

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/09/2017 Hour : 08:34 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	