

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	101620 KM
File nr. :	1435626	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GBY588 / VF3YCPMFC12344036 /		yr of constructionr :	/
E-File nr. :		First registration :	20/12/2013
VFS-nr. :		Color :	WHITE
Make + Model :	PEUGEOT / BOXER	Fuel type :	DIESEL
Object nr. :	69615	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	V W AUTOMATIQUE SCRL	Co2:	224g/km
Driver :		Remote controls:	1
Covering :	IMITATION LEATHER	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	BOXER 335 B/F LWB L3H2 177PK FAP	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	BESTELWAGEN	Engine size:	2999
Gear box :	Manueel	Number of places:	3
Number of gears:	6	Number of doors:	5
HP:	177	kW:	130
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	4-6/	Rim :	/
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	70	R	15	
Rear tyre	215	70	R	15	

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]		REAR BUMPER/SIDE/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE		
Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR	110.64 EUR
[x]		REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE		+DEUKEN
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR

Interior

[x]		REAR MIRROR	OTHER DAMAGES		
		Repair paint - LI	New paint - E	Depr.	Total
4	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 3	bestelwagen-cabine-a-vab-rein-05	CLEANING INTERIOR	11.47 EUR	34.41 EUR

1	2	3	4	5	6	7	8	9	10
34.41	231.15	110.64	24.00	0	0	0	0	0	0
34.41	115.58	110.64	12.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
145.05	255.15	0	400.20
HOG: 0	BG: 3		NA Deprec. 272.62
			0.00%
			TOTAL 272.62

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 11/09/2017 Hour : 07:25 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	