

www.vabfleetservices.be Date: 14/09/2017 1/4

CKITZG

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: DIRTY [x] Owner: Mileage : 196083 KM File nr. : Mileage start / arrival: 0 / 01436798 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1EYA128 / WBA3L11010F282314 / E-File nr. : First registration: 18/04/2013 VFS-nr.: Color: **GREY** Make + Model : Fuel type : BMW / 3 TOURING **DIESEL** Object nr. : Fuel: 43925 **Environment Class:** Classification: EURO 5 Customer company: Co2: BAXTER SERV.EUROPE SA 112g/km Driver : Remote controls: 2 LEATHER Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type: 3 TOURING 320dA Eff.Dyn.Ed.163PK Aut. Country registration: **BELGIUM**

VAT over the margin - car:	No	Metallic paint:	Yes				
Variant car:	BREAK	Engine size:	1995				
Gear box :	Automaat algemeen	Number of places:	5				
Number of gears:		Number of doors:	5				
нр:	163	kW:	120				
Fisc HP		Imported vehicle:					
Animals transported:	No	Smoked in vehicle:	No				
Due date vehicle inspection:		Extra set of tires:	No				
		Use:	Unknown				
General condition:							



www.vabfleetservices.be Date: 14/09/2017 2/4

Original registr. number :	OK		Service manual :				
Cert. of reg. / Part 1:			Cert. of conformity:	OK			
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :				
Warning vest :	OK	[x]	Transport licence :	Transport licence :			
Tax certificate :			Navigation CD/SD/DVD		[x]		
Fuel card :			Car radio :	OK	[x]		
Mobile phone kit :			Extinguisher :	OK	[x]		
			Warning triangle :	OK	[x]		
First aid kit :	OK	[x]	Oil level :	OK	[x]		
Jack, wheelspanner :	OK	[x]	Filled up :	0			

Wheels and tyres: Summer tires

Front tyre			205			6	50		R		16		W
[x] Width		Width			He	ight			Туре		Rim	Index	
Wheel RES:	[x]		Tyre:		OK		/	Rim:				/ Hubcap:	
Wheel RR:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel FR:	[x]	MICHELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel RL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel FL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap :	

	Front tyre	205	60	R	16	W
	Rear tyre	205	60	R	16	W
ı						

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 14/09/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[X] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

[x] REAR MUDGUARD/RIGHT/FRONT DENT 2X

[x] FRONT DOOR/RIGHT/CENTER DENT 3X

[x] FRONT BUMPER/LEFT SCRATCH WITH PAINT DAMAGE

Interior

[x] SEAT FL OTHER DAMAGES

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	0	0		0
HOG: 0	BG: 0		NA Deprec.	0
			0.00%	
			TOTAL	0



www.vabfleetservices.be Date: 14/09/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS	TANCES		UNDER CONDITION - DUSTY VEHICLE					
Extra Time :	0 min	Waiting time: 0 min Reason:	1	Towing time : Reason :	0 min			
NOT EXECUTED : Reason :	No	I						
Remark :								
Prices in EUR v	vithout VAT							
Authorized by customer :			Executed by VAB Flee	t Services				
Remark authorized	customer :							
Date :	14/09/2017	Hour: 09:00						
Company : Executed by VAB F Services	leet							
Services E-Mail:	@							
Signature authorized	by customer	_	+					