

www.vabfleetservices.be Date: 20/09/2017 1/4

CQ991L

[X] EFFECTIVE [] NOT EXECUTED [] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	95193 KM
File nr. :	1441214	Mileage start / arrival:	0/0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FSG901 / WAUZZZ8K3EA0	049988 /	yr of constructionr :	/
E-File nr. :		First registration :	09/10/2013
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / A4 AVANT	Fuel type :	DIESEL
Object nr. :		Fuel:	
Classification:	F	Environment Class:	EURO 5
Customer company :	GLOBAL PIPELINE SOLUTIONS	Co2:	129g/km
Driver :		Remote controls:	1
Covering :	LEATHER	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

	· ·	•	
Variant car:	BREAK	Engine size:	1968
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	150	kW:	110
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Metallic paint:

Yes



www.vabfleetservices.be Date: 20/09/2017 2/4

Original registr. number :			Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Winter tires

	[x] Width Height		Туре		Rim	Index						
Wheel RES:	[x]		Tyre:		OK		/	Rim:		/	Hubcap:	
Wheel RR:	[x]	KLÉBER	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel FR:	[x]	KLÉBER	Tyre:	[x]	OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel RL:	[x]	KLÉBER	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wheel FL:	[x]	KLÉBER	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:	

	[x]	Width	Height	Type	Rim	Index
Front tyre		225	55	R	16	M+S
Rear tyre		225	55	R	16	M+S

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

[x]	[x] Width		Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 20/09/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

[x] REAR BUMPER/CENTER/RIGHT

SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

[x] REAR DOOR/LEFT/FRONT DENT

 Repair paint - LI
 New paint - E
 Depr.
 Total

 1 15 LU = 72.00 EUR
 318.35 EUR
 50 %
 390.35 EUR

[X] ROOF/REAR/LEFT OTHER DAMAGES CHEMISCHE INWERKING

 Repair paint - LI
 New paint - E
 Depr.
 Total

 2 0 LU = 0.00 EUR
 481.50 EUR
 50 %
 481.50 EUR

FRONT BUMPER/LEFT/SIDE OTHER DAMAGES SLECHTE HERSTELLING

Number Code Description Unit price Depr. Total

0 0

[x]

1	2	3	4	5	6	7	8	9	10
390.35	481.50	0	0	0	0	0	0	0	0
195.18	240.75	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	871.85	0		871.85
HOG: 0	BG: 0		NA Deprec.	435.92
			0.00%	

TOTAL 435.92



www.vabfleetservices.be Date: 20/09/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS	STANCES		NORMAL CONCLUSION				
Extra Time :	0 min	Waiting time: 0 mi Reason:	n	Towing time : Reason :	0 min		
NOT EXECUTED Reason:): No						
Remark:	1						
Prices in EUR	without VAT						
Authorized by customer:			Executed by VAB Flee	et Services			
Remark authorized	d customer :						
Date :	20/09/2017	Hour: 11:02					
Company: Executed by VAB	Fleet						
Services E-Mail :	@						
Signature authorized	d by customer						