

CNUXZG

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	116564 KM
File nr. :	1439389	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ENP378 / WBA3K91080F868655 /		yr of constructionr :	/
E-File nr. :		First registration :	31/01/2013
VFS-nr. :		Color :	BROWN
Make + Model :	BMW / 3 TOURING	Fuel type :	DIESEL
Object nr. :	37802	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KBC GROEP NV	Co2:	123g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	[x]
Fuel card :	[x]	Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	FIRESTONE	Tyre :	OK	4-6/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	FIRESTONE	Tyre :	OK	[x] 2-4/	Rim :	[x]	/	Hubcap :
Wheel FR :	FIRESTONE	Tyre :	OK	4-6/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	FIRESTONE	Tyre :	OK	[x] 2-4/	Rim :	[x]	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	225	55	R	16	W
Rear tyre	225	55	R	16	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR MUDGUARD/LEFT/CENTER SCRATCH WITH PAINT DAMAGE
- [x] REAR DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

	Repair paint - LI	New paint - E	Depr.	Total
[x] REAR BUMPER/CENTER/RIGHT 2 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x] REAR MUDGUARD/RIGHT/FRONT 1 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR
[x] FRONT BUMPER/RIGHT/SIDE 3 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Interior

	Repair paint - LI	New paint - E	Depr.	Total
[x] LUGGAGE COVER 4 0 LU =0.00 EUR	0.00 EUR		50 %	

1	2	3	4	5	6	7	8	9	10
308.20	211.80	211.80	0.00	0	0	0	0	0	0
154.10	105.90	105.90	0.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	731.80	0	731.80
HOG: 0	BG: 0		NA Deprec. 365.90
			0.00%
			TOTAL 365.90

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 15/09/2017 Hour : 10:20 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	