

www.vabfleetservices.be Date: 15/09/2017 1/4

CMIVOV

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	169676 KM
File nr. :	1438374	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GFV075 / WBA5C11040D03	5504 /	yr of constructionr :	/
E-File nr. :		First registration :	28/01/2014
VFS-nr. :		Color :	GREY
Make + Model :	BMW / 5	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification:		Environment Class:	EURO 6
Customer company :	BELGACOM INS/FLEET NV	Co2:	119g/km
Oriver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	5 BER 518d 136PK	Country registration :	BELGIUM

		_					
Variant car:	BERLINE	Engine size:	1995				
Gear box :	Manueel	Number of places:	5				
Number of gears:	6	Number of doors:	4				
нр:	136	kW:	100				
Fisc HP		Imported vehicle:					
Animals transported:	No	Smoked in vehicle:	No				
Due date vehicle inspection:		Extra set of tires:					
		Use:	Unknown				
General condition:							

Metallic paint:

Yes



www.vabfleetservices.be Date: 15/09/2017 2/4

Original registr. number: OK Service manual:

Cert. of reg. / Part 1: OK [x] Cert. of conformity: OK

Cert. of reg. copy / Part 2: Insurance certificate :

Warning vest : Transport licence :
Tax certificate : Navigation CD/SD/DVD

Fuel card: Car radio: OK [x]

Mobile phone kit: Extinguisher: OK [x]

Warning triangle : OK [x]

First aid kit: OK [x] Oil level: OK [x]

Jack, wheelspanner: Filled up: 0

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:
Wheel RL:	[x]	GOODYEAR	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:
Wheel FR:	[x]	GOODYEAR	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:
Wheel RR:	[x]	GOODYEAR	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:
Wheel RES:	[x]		Tyre:		OK		/	Rim:			/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	225	55	R	17	Н
Rear tyre	225	55	R	17	Н

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 15/09/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[X] REAR BUMPER/SIDE/LEFTCENTER SCRATCH WITH PAINT DAMAGE

[x] WINDSCREEN/CENTER/LEFT CHIPS

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	0	0		0
HOG: 0	BG: 2		NA Deprec.	0
			0.00%	
			TOTAL	0



www.vabfleetservices.be Date: 15/09/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS			NORMAL CONCLUSION						
Extra Time :	0 min	Waiting time : Reason :	0 min		Towing time : Reason :	0 min			
NOT EXECUTED : Reason :	: No				<u> </u>				
Remark :									
Prices in EUR v	vithout VAT								
Authorized by customer :				Executed by VAB Fleet S	ervices				
Remark authorized	customer :								
Date :	15/09/2017	Hour: 12:	07						
Company : Executed by VAB F Services	leet								
E-Mail:	@								
Signature authorized	by customer								
,									