

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	104683 KM
File nr. :	1435950	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ELJ043 / WBAMX11000C978026 /		yr of constructionr :	/
E-File nr. :		First registration :	14/01/2013
VFS-nr. :		Color :	BLUE
Make + Model :	BMW / 5	Fuel type :	DIESEL
Object nr. :	12067	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	DELOITTE BEDRIJFSREVISOREN/REVISEURS CVA	Co2:	130g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	5 TOURING 520d Start/Stop 163PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1: OK [x]	Cert. of conformity : OK
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher :
First aid kit :	Warning triangle : OK [x]
Jack, wheelspanner : OK [x]	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] GOODYEAR Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] GOODYEAR Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel FR : [x] GOODYEAR Tyre : [x] OK [x] 2-4/ Rim : / Hubcap :
Wheel RR : [x] GOODYEAR Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RES: [x] ANDERE Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	W
Rear tyre	225	55	R	17	W

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] THRESHOLD FRONT/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/RIGHT/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

[x] REAR MUDGUARD/RIGHT/REAR DENT

	Repair paint - LI	New paint - E	Depr.	Total
3 10 LU =48.00 EUR	369.84 EUR		50 %	417.84 EUR

[x] FRONT BUMPER/CENTER/LEFT DENT

	Repair paint - LI	New paint - E	Depr.	Total
2 10 LU =48.00 EUR	254.16 EUR		50 %	302.16 EUR

Interior

[x] FLOOR BOOT STAIN

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR

Others

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
14.58	302.16	672.00	95.00	0	0	0	0	0	0
14.58	151.08	336.00	95.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
109.58	974.16	0	1083.74
HOG: 0	BG: 2		NA Deprec. 596.66
			0.00%
			TOTAL 596.66

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 19/09/2017 Hour : 10:12 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer <hr/>	