

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	144690 KM
File nr. :	1428324	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FWF410 / WBA1C91060J518250 /		yr of constructionr :	/
E-File nr. :		First registration :	15/11/2013
VFS-nr. :		Color :	GREY
Make + Model :	BMW / 1	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	1 HATCH 116d Eff.Dyn.Ed. 116PK	Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	Yes
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1: OK [x]	Cert. of conformity : OK
Cert. of reg. copy / Part 2: NOK [x]	Insurance certificate :
Warning vest : OK [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN	Tyre : OK [x] 2-4/	Rim : [x] WHEEL SCRATCHED	Hubcap :
Wheel RL : [x] MICHELIN	Tyre : OK [x] 2-4/	Rim : [x] WHEEL SCRATCHED	Hubcap :
Wheel FR : [x] MICHELIN	Tyre : [x] OK [x] 2-4/	Rim : [x] WHEEL SCRATCHED	Hubcap :
Wheel RR : [x] MICHELIN	Tyre : OK [x] 2-4/	Rim : [x] WHEEL SCRATCHED	Hubcap :
Wheel RES: [x]	Tyre : [x] NOK /	Rim :	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	W
Rear tyre	205	55	R	16	V

Remark : FLANC PNEU ARD FORTEMENT ENTAILLE

Wheels and tyres:

Wheel FL:	Tyre : OK /	Rim :	Hubcap :
Wheel RL :	Tyre : OK /	Rim :	Hubcap :
Wheel FR :	Tyre : OK /	Rim :	Hubcap :
Wheel RR :	Tyre : OK /	Rim :	Hubcap :
Wheel RES:	Tyre : OK /	Rim :	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/CENTER/LEFT	OTHER DAMAGES	INFILTRATION EAU INT COFFRE
[x]	REAR DOOR/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE	POLIR
[x]	REAR DOOR/RIGHT/CENTER	DENT	
[x]	FRONT MUDGUARD/RIGHT/CENTER	DENT	2X

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/SIDE/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
7	25 LU =120.00 EUR	211.80 EUR		50 %	331.80 EUR
[x]	REAR MUDGUARD/LEFT/CENTER	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
7	20 LU =96.00 EUR	308.20 EUR		50 %	404.20 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
8	5 LU =24.00 EUR	308.20 EUR		50 %	332.20 EUR
[x]	ROOF STYLE/CENTER/LEFT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
5	I 1 i-vab-uitd-03	BEAT OUT DENT (HAIL DAMAGE)	97.80 EUR		97.80 EUR
[x]	ROOF STYLE/CENTER/RIGHT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
5	I 1 i-vab-uitd-03	BEAT OUT DENT (HAIL DAMAGE)	97.80 EUR		97.80 EUR
[x]	REAR DOOR/RIGHT/FRONT	DENT		4X	
		Repair paint - LI	New paint - E	Depr.	Total
5	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
10	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

[x]	BONNET/CENTER/LEFT		DENT			
Number	Code	Description	Unit price	Depr.	Total	
5	I 1 i-vab-uitd-03	BEAT OUT DENT (HAIL DAMAGE)	97.80 EUR		97.80 EUR	
Number	Code	Description	Unit price	Depr.	Total	
5	I 1 i-vab-uitd-03	BEAT OUT DENT (HAIL DAMAGE)	97.80 EUR		97.80 EUR	

[x]	FRONT BUMPER/RIGHT/CORNER		DENT		+MISTLAMP	
		Repair paint - LI	New paint - E	Depr.	Total	
6	20 LU =96.00 EUR	211.80 EUR		50 %	307.80 EUR	

[x]	ROOF/CENTER/LEFT		DENT			
Number	Code	Description	Unit price	Depr.	Total	
5	I 1 i-vab-uitd-03	BEAT OUT DENT (HAIL DAMAGE)	97.80 EUR		97.80 EUR	
Number	Code	Description	Unit price	Depr.	Total	
5	I 1 i-vab-uitd-03	BEAT OUT DENT (HAIL DAMAGE)	97.80 EUR		97.80 EUR	

Interior

[x]	CENTER CONSOLE		MISSING/INCOMPLETE			
		Repair paint - LI	New paint - E	Depr.	Total	
2	0 LU =0.00 EUR	0 EUR		50 %		

[x]	FLOOR FL		BURNT			
Number	Code	Description	Unit price	Depr.	Total	
1	I 1 i-vab-inttap-01	CARPET REPAIR (MAX 3CM LENGTH OR DIAMETER)	43.92 EUR		43.92 EUR	

[x]	FLOOR FR		BURNT			
Number	Code	Description	Unit price	Depr.	Total	
4	I 1 i-vab-inttap-01	CARPET REPAIR (MAX 3CM LENGTH OR DIAMETER)	43.92 EUR		43.92 EUR	

Others

	TYRE SPARE WHEEL					
		Repair paint - LI	New paint - E	Depr.	Total	
3	0 LU =0.00 EUR			50 %		

	RIM FRONT LEFT					
Number	Code	Description	Unit price	Depr.	Total	
9	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR	

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
9	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
9	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	DOPE 12V	18.00 EUR	50 %	18.00 EUR
3	1	LIJM REPARATIE KIT	35.00 EUR	50 %	35.00 EUR
10	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR

1	2	3	4	5	6	7	8	9	10
43.92	18.00	35.00	43.92	649.80	307.80	736.00	332.20	285.00	487.20
43.92	9.00	17.50	43.92	649.80	153.90	368.00	166.10	285.00	243.60

INNOVATIVE	TRADITIONAL	GENERAL	
1022.64	1916.20	0	2938.84
HOG: 0	BG: 0		NA Deprec. 1980.74
			0.00%
			TOTAL 1980.74

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : CERTIFICAT IMMAT AU NOM DE BELGACOM/LE CLIENT DOIT FAIRE PARVENIR LA PARTIE 2 [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 18/09/2017 Hour : 11:50 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	