

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	135246 KM
<b>File nr. :</b>	1438809	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FHG363 / WF0MXXGBWMDJ88945 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	15/04/2013
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	FORD / GALAXY	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	74419	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	BRUSSELS AIRPORT COMPANY NV	<b>Co2:</b>	139g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	GALAXY Econetic Ghia St&St DPF 115PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	
<b>Variant car:</b>		<b>Engine size:</b>	
<b>Gear box :</b>		<b>Number of places:</b>	
<b>Number of gears:</b>		<b>Number of doors:</b>	
<b>HP:</b>		<b>kW:</b>	
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	
<b>General condition:</b>			

Original registr. number :	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity :
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio :
Mobile phone kit :	Extinguisher :
First aid kit :	Warning triangle :
Jack, wheelspanner :	Oil level :
	Filled up : 0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x] WHEEL SCRATCHED / Hubcap :
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	[x] WHEEL SCRATCHED / Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	W
Rear tyre	225	50	R	17	W

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/LEFT/Front	SCRATCH WITH PAINT DAMAGE
[x]	REAR BUMPER/SIDE/RIGHT/Front	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/RIGHT/Front	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	WINDSCREEN/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/LEFT/Front	SCRATCH WITH PAINT DAMAGE

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE				
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
5	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
[x]	REAR WINDOW STYLE/CENTER/LEFT/UP	SCRATCH WITH PAINT DAMAGE				
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
6	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR
[x]	FRONT DOOR/LEFT/Front	SCRATCH WITH PAINT DAMAGE				
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
4	0 LU =0.00 EUR		382.02 EUR		50 %	382.02 EUR
[x]	FRONT MUDGUARD/LEFT/Front	SCRATCH WITH PAINT DAMAGE				
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
3	0 LU =0.00 EUR		264.21 EUR		50 %	264.21 EUR
[x]	BONNET/CENTER/RIGHT	OTHER DAMAGES			ISOLATIE	
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
1	5 LU =24.00 EUR		0 EUR		50 %	24.00 EUR

[x]	FRONT BUMPER/RIGHT		SCRATCH WITH PAINT DAMAGE			
Number	Code	Description	Unit price	Depr.	Total	
2	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR	

## Interior

[x]	LUGGAGE COVER		MISSING/INCOMPLETE			
		Repair paint - LI	New paint - E	Depr.	Total	
1	0 LU =0.00 EUR	0 EUR		50 %		

[x]	DOOR IN FL		CUT / TORN			
Number	Code	Description	Unit price	Depr.	Total	
1	I 1 i-vab-intdash-01	PLASTICS REPAIR INTERIRO	110.64 EUR		110.64 EUR	

[x]	DOOR IN REAR L		OTHER DAMAGES			
Number	Code	Description	Unit price	Depr.	Total	
1	I 4 i-vab-ander-01	REPAIR (PER 15')	18.74 EUR		74.96 EUR	

## Others

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total	
7	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR	

## Pieces

Number	Code	Description	Unit price	Depr.	Total	
1	1 ISOLATIE		50.00 EUR	50 %	50.00 EUR	

Number	Code	Description	Unit price	Depr.	Total	
1	1 LUGGAGE COVER		288.00 EUR	50 %	288.00 EUR	

1	2	3	4	5	6	7	8	9	10
547.60	115.56	264.21	382.02	110.64	115.56	95.00	0	0	0
366.60	115.56	132.10	191.01	110.64	115.56	95.00	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
622.36	1008.23	0	1630.59
HOG: 0	BG: 2		NA Deprec. 1126.48
			0.00%
			<b>TOTAL 1126.48</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 18/09/2017 <b>Hour :</b> 15:49 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b>  	