

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	117323 KM
File nr. :	1427487	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EZF269 / WDD2040001A863946 /		yr of constructionr :	/
E-File nr. :		First registration :	26/04/2013
VFS-nr. :		Color :	GREY
Make + Model :	MERCEDES / C	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	127g/km
Driver :		Remote controls:	2
Covering :	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	C BER 180 CDI BlueEFF. S&S 120PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	2143
Gear box :	Manueel	Number of places:	4
Number of gears:	6	Number of doors:	4
HP:	120	kW:	88
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	Yes
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	VREDESTEIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	VREDESTEIN	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED / Hubcap :	
Wheel FR :	[x]	VREDESTEIN	Tyre :	[x]	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED / Hubcap :
Wheel RR :	[x]	VREDESTEIN	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED / Hubcap :	
Wheel RES:	[x]	ANDERE	Tyre :	OK	/		Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

Conclusion

Bodywork \& windows

[x]	REAR DOOR/RIGHT/FRONT	OTHER DAMAGES	SL HERST OVB
[x]	FRONT DOOR/RIGHT/CENTER	OTHER DAMAGES	HERSTELD OVB

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR DOOR/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR DOOR/LEFT/FRONT	DENT	
[x]	REAR DOOR/RIGHT/CENTER	DENT	
[x]	FRONT DOOR/LEFT/REAR	DENT	
[x]	WINDSCREEN/CENTER/RIGHT	WINDOW DAMAGE	HERSTELD
[x]	FRONT THRESHOLD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	INSTAP
[x]	BONNET/CENTER/LEFT	DENT	
[x]	FRONT MUDGUARD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	BONNET/LEFT/FRONT	DENT	
[x]	FRONT BUMPER/LEFT	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE	

Interior

[x]	CARPET FL	HOLE	
[x]	DOOR IN FL	SCRATCHED	
[x]	DOOR IN FR	SCRATCHED	
[x]	DOOR IN REAR L	SCRATCHED	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER		DENT		+KRASSEN+ CHROOMLIJST				
				Repair paint - LI	New paint - E		Depr.	Total	
5	5 LU =24.00 EUR			211.80 EUR			50 %	235.80 EUR	
[x]	REAR MUDGUARD/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE						
				Repair paint - LI	New paint - E		Depr.	Total	
4	0 LU =0.00 EUR			308.20 EUR			50 %	308.20 EUR	
[x]	FRONT MUDGUARD/LEFT/CENTER		DENT						
				Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-uitd-01	BEAT OUT DENT			63.00 EUR		63.00 EUR	
				Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-uitd-02	BEAT OUT DENT SUPPL			19.80 EUR		19.80 EUR	
[x]	FRONT BUMPER/LEFT/CORNER		HOLE/CRACK/TORN					CHROOMLIJSTEN	
				Repair paint - LI	New paint - E		Depr.	Total	
2	5 LU =24.00 EUR			0 EUR			50 %	24.00 EUR	

Interior

[x]	FLOOR FL		BURNT						
				Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-inttap-01	CARPET REPAIR (MAX 3CM LENGTH OR DIAMETER)			43.92 EUR		43.92 EUR	
				Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-inttap-02	SUPPL REPAIR CARPET			18.00 EUR		18.00 EUR	
[x]	CARPET REAR RIGHT		MISSING/INCOMPLETE						
				Repair paint - LI	New paint - E		Depr.	Total	
1	0 LU =0.00 EUR			0 EUR					
[x]	SEAT REAR RIGHT		BURNT						
				Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-intvtr-01	VELOURS REPAIR (MAX 3CM LENGTH OR DIAMATER)			64.32 EUR		64.32 EUR	
[x]	DOOR IN REAR RIGHT		CUT / TORN						
				Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-intdash-01	PLASTICS REPAIR INTERIRO			110.64 EUR		110.64 EUR	

[x]	ROOF UPHOLSTERY		BURNT		
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
[x]	BOOT LID IN		CUT / TORN		
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR	0 EUR			24.00 EUR

Others

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	BEKL KOFFER	35.00 EUR		35.00 EUR
1	1	CARPET	25.00 EUR		25.00 EUR
1	1	BEKL A-STIJL	40.00 EUR	50 %	40.00 EUR
2	1	CHROOMLIJST	45.00 EUR	50 %	45.00 EUR
2	1	CHROOMLIJST MISTLICHT	65.00 EUR	50 %	65.00 EUR
5	1	CHROOMLIJST	50.00 EUR	50 %	50.00 EUR

1	2	3	4	5	6	7	8	9	10
384.88	134.00	82.80	308.20	285.80	95.00	0	0	0	0
352.88	67.00	82.80	154.10	142.90	95.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
414.68	876.00	0	1290.68
HOG: 0	BG: 0		NA Deprec. 894.68
			0.00%
			TOTAL 894.68

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 18/09/2017 Hour : 14:42 Company : Executed by VAB Fleet Services E-Mail :	Executed by VAB Fleet Services
Signature authorized by customer 	