

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	123474 KM
<b>File nr. :</b>	1436761	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1EPZ514 / WDD2042001G066160 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	19/02/2013
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	MERCEDES / C BREAK	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	BELGACOM INS/FLEET NV	<b>Co2:</b>	127g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE-LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	C BRE 180 CDI BlueEFF. S&S 120PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BREAK	<b>Engine size:</b>	2143
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	120	<b>kW:</b>	88
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

<b>Original registr. number :</b> OK	<b>Service manual :</b> OK [x]
<b>Cert. of reg. / Part 1:</b> OK [x]	<b>Cert. of conformity :</b> OK
<b>Cert. of reg. copy / Part 2:</b>	<b>Insurance certificate :</b> [x]
<b>Warning vest :</b> OK [x]	<b>Transport licence :</b>
<b>Tax certificate :</b>	<b>Navigation CD/SD/DVD</b>
<b>Fuel card :</b>	<b>Car radio :</b> OK [x]
<b>Mobile phone kit :</b>	<b>Extinguisher :</b> OK [x]
<b>First aid kit :</b> OK [x]	<b>Warning triangle :</b> OK [x]
<b>Jack, wheelspanner :</b> OK [x]	<b>Oil level :</b> OK [x]
	<b>Filled up :</b> 0

## Wheels and tyres: Summer tires

<b>Wheel FL:</b> [x] PIRELLI <b>Tyre :</b> OK [x] 1.6-2/ <b>Rim :</b> [x] WHEEL SCRATCHED / <b>Hubcap :</b>
<b>Wheel RL :</b> [x] BRIDGESTONE <b>Tyre :</b> OK [x] 4-6/ <b>Rim :</b> [x] WHEEL SCRATCHED / <b>Hubcap :</b>
<b>Wheel FR :</b> [x] PIRELLI <b>Tyre :</b> [x] OK [x] 1.6-2/ <b>Rim :</b> [x] WHEEL SCRATCHED / <b>Hubcap :</b>
<b>Wheel RR :</b> [x] BRIDGESTONE <b>Tyre :</b> OK [x] 4-6/ <b>Rim :</b> [x] WHEEL SCRATCHED / <b>Hubcap :</b>
<b>Wheel RES:</b> [x] ANDERE <b>Tyre :</b> OK [x] 2-4/ <b>Rim :</b> / <b>Hubcap :</b>

  

[x]	Width	Height	Type	Rim	Index
<b>Front tyre</b>	205	55	R	16	V
<b>Rear tyre</b>	205	55	R	16	V

**Remark :**

## Wheels and tyres:

<b>Wheel FL:</b> <b>Tyre :</b> OK / <b>Rim :</b> / <b>Hubcap :</b>
<b>Wheel RL :</b> <b>Tyre :</b> OK / <b>Rim :</b> / <b>Hubcap :</b>
<b>Wheel FR :</b> <b>Tyre :</b> OK / <b>Rim :</b> / <b>Hubcap :</b>
<b>Wheel RR :</b> <b>Tyre :</b> OK / <b>Rim :</b> / <b>Hubcap :</b>
<b>Wheel RES:</b> <b>Tyre :</b> OK / <b>Rim :</b> / <b>Hubcap :</b>

  

[x]	Width	Height	Type	Rim	Index
<b>Front tyre</b>	0	0	R	0	
<b>Rear tyre</b>	0	0	R	0	

**Remark :**

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR DOOR/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	POL.
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT DOOR/LEFT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS	

### Interior

[x]	CENTER CONSOLE	OTHER DAMAGES
[x]	SEAT FL	OTHER DAMAGES

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	MEERDERE KRASSEN				
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>		
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR		
[x]	REAR MUDGUARD/RIGHT/CENTER	DENT					
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>		
4	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR		
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE					
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>		
5	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR		
[x]	FRONT BUMPER/LEFT/CORNER	HOLE/CRACK/TORN					
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>		
2	20 LU =96.00 EUR	0 EUR	235.80 EUR	50 %	331.80 EUR		
[x]	WIND SCREEN/BELOW/RIGHT	WINDOW DAMAGE					
		<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
1	I 1	i-vab-herstr-01		WINDOW REPAIR	58.80 EUR		58.80 EUR

## Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

## Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	FRONT BUMPER	403.20 EUR	50 %	403.20 EUR

1	2	3	4	5	6	7	8	9	10
58.80	830.00	211.80	308.20	318.35	0	0	0	0	0
58.80	462.50	105.90	154.10	159.18	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
153.80	1573.35	0	<b>1727.15</b>
HOG: 0	BG: 0		NA Deprec. 940.48
			0.00%
			<b>TOTAL 940.48</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b> NAVI OK [x]		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 14/09/2017 <b>Hour :</b> 10:45 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	