

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	126917 KM
<b>File nr. :</b>	1429134	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1DPF607 / W0LPD9EM7C2113485 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	12/07/2012
<b>VFS-nr. :</b>		<b>Color :</b>	BLUE
<b>Make + Model :</b>	OPEL / ZAFIRA	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	KBC ASSET MANAGEMENT NV (GROEP AMB)	<b>Co2:</b>	119g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	ZAFIRA TOURER ecoFL.Enjoy St/St.130PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1956
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	131	<b>kW:</b>	96
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	OK	[x]	
Cert. of reg. / Part 1:		Cert. of conformity :	OK		
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	OK	[x]
Warning vest :		Transport licence :			
Tax certificate :		Navigation CD/SD/DVD	OK	[x]	
Fuel card :		Car radio :	OK	[x]	
Mobile phone kit :		Extinguisher :	OK	[x]	
First aid kit :	OK	[x]	Warning triangle :	OK	[x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK	[x]
		Filled up :	0		

## Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	1.6-2/	Rim :	[x]	BROKEN DOWN / DAMAGED	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	1.6-2/	Rim :	/	Hubcap :			
Wheel RES:	[x]	MICHELIN	Tyre :	OK		/	Rim :	/	Hubcap :			

  

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	V
Rear tyre	225	50	R	17	V

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT	
[x]	REAR THRESHOLD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	+DEUK/INTERIEUR
[x]	REAR DOOR/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR THRESHOLD/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	INTERIEUR
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	THRESHOLD FRONT/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	INTERIEUR
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	FRONT THRESHOLD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	INTERIEUR
[x]	FRONT MUDGUARD/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	FRONT MUDGUARD/LEFT/FRONT	DENT	
[x]	FRONT MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT BUMPER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)	

### Interior

[x]	CENTER CONSOLE	CUT / TORN	
-----	----------------	------------	--

### Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH WITH PAINT DAMAGE	
-----	-------------------------------	---------------------------	--

## STATUS: NOT ACCEPTABLE

### Others

RIM REAR LEFT

	Repair paint - LI	New paint - E	Depr.	Total
1 5 LU =24.00 EUR			50 %	24.00 EUR

### Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	STEEL WHEEL	64.80 EUR	50 %	64.80 EUR

1	2	3	4	5	6	7	8	9	10
88.80	0	0	0	0	0	0	0	0	0
44.40	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	88.80	0	<b>88.80</b>
HOG: 0	BG: 0		NA Deprec. 44.40
			0.00%
			<b>TOTAL 44.40</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b> OVBH HEVIGE REGEN [x]		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 18/08/2017 <b>Hour :</b> <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	