

CLTVRN

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	73761 KM
File nr. :	1437824	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1LEZ315 / YV1DZ73C1F2710021 /		yr of constructionr :	/
E-File nr. :		First registration :	09/09/2015
VFS-nr. :		Color :	GREY
Make + Model :	VOLVO / XC60	Fuel type :	DIESEL
Object nr. :	706498	Fuel :	
Classification :		Environment Class:	EURO 6
Customer company :	CVBA VERKOOP EN FABRICATIE VAN METAALPRO	Co2:	117g/km
Driver :		Remote controls:	2
Covering :	TISSUE-LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	1969
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	181	kW:	133
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	>6/	Rim :	/
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	235	65	R	17	V
Rear tyre	235	65	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total	
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR	
[x]	REAR DOOR/LEFT/Front		DENT			
		Repair paint - LI	New paint - E	Depr.	Total	
1	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR	
[x]	BONNET/CENTER/RIGHT		OTHER DAMAGES		SLECHTE HERSTELLING	
	Number	Code	Description	Unit price	Depr.	Total
0	0					
[x]	FRONT BUMPER/RIGHT/CORNER		HOLE/CRACK/TORN			
		Repair paint - LI	New paint - E	Depr.	Total	
3	0 LU =0.00 EUR	0 EUR		50 %		
		Repair paint - LI	New paint - E	Depr.	Total	
3	20 LU =96.00 EUR	0 EUR	235.80 EUR	50 %	331.80 EUR	

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
4	I2	personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR	22.94 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	FRONT BUMPER	403.20 EUR	50 %	403.20 EUR

1	2	3	4	5	6	7	8	9	10
318.35	211.80	735.00	22.94	0	0	0	0	0	0
159.18	105.90	367.50	22.94	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
22.94	1265.15	0	1288.09
HOG: 0	BG: 0		NA Deprec. 655.52
			0.00%
			TOTAL 655.52

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 14/09/2017 Hour : 13:36 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	